





report date: 2024-03-28

General information

Make	MAZDA
Model	CX-5 D SPORT NAV
Colour	White
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-15

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-14

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-12
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5	2023-07-12 10:04
MOT test number	582403043577
Result	✓ Passed
Next expiry date	2024-07-12

MOT #4	2022-07-05 11:39
MOT test number	807991008886
Result	✓ Passed

MOT #3	2021-07-13 06:45
MOT test number	465492360166
Result	✓ Passed
Advice ALL FOUR BRAKE DISC HAVE SURFACE CORROSION	

CarCheck.co.uk page 3/11



VN67VZL

report date: 2024-03-28

MOT #2 2020-11-24 09:11 759564009391 **MOT test number** Result ✓ Passed Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Nearside Rear Nail in tyre Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge tread depth 2mm + worn on inner edge (5.2.3 (e)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Central Front Items removed from driver's view prior to test Offside Front Tyre worn close to legal limit/worn on edge tread depth 2mm + worn on inner edge Advice (5.2.3 (e))

MOT #1	2020-11-24 09:11
MOT test number	208989277648
Result	X Failed
Advice Nearside Rear Nail in tyre	
Pass with rectification Windscreen was	her provides insufficient washer liquid (3.5 (a))
Advice Nearside Rear Child Seat fitted no	t allowing full inspection of adult belt
Advice Nearside Front Tyre worn close to legal limit/worn on edge tread depth 2mm + worn on inner edge (5.2.3 (e))	
Advice Central Front Items removed from	driver's view prior to test
Advice Offside Front Tyre worn close to le (5.2.3 (e))	gal limit/worn on edge tread depth 2mm + worn on inner edge
Advice Offside Rear Child Seat fitted not a	allowing full inspection of adult belt

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e united this test	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-27
Last registration	2023-07-12
Complete history	See info



Registration #1	2017-11-27	20 mi
Registration #2	2020-11-24	57.754 mi
Registration #3	2020-11-24	57.754 mi
Registration #4	2021-07-13	66.810 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

page 10/11 CarCheck.co.uk



Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Wheel base	2700 mm
Kerb weight	1594 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30772423

CarCheck.co.uk page 11/11