



BT05ZBD

report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO X 600 D P/V
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	71 BHP
Max. torque	125 Nm at 2.500 rpm
Engine capacity	1.868 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-09-16
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	51
Total items failed	23

MOT #20	2020-09-15 13:22
MOT test number	856441584432
Result	✓ Passed
Next expiry date	2021-09-16
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))



MOT #19

2020-09-15 13:22

MOT test number

151689408684

Result

✗ Failed

Pass with rectification Offside Front Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

Pass with rectification Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

Pass with rectification Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Pass with rectification Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #18

2019-09-14 09:13

MOT test number

283825171027

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #17**

2019-09-14 09:13

MOT test number

415453859394

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16

2018-09-17 08:30

MOT test number

728145748712

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15**

2018-09-13 11:32

MOT test number

144594147009

Result

✗ Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #14**

2017-09-16 11:12

MOT test number

575974506046

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13**

2016-09-06 14:37

MOT test number

478781412367

Result

✓ Passed

Advice Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Offside Rear tyre perishing on sidewalls

**MOT #12**

2016-08-30 09:05

MOT test number

742575899107

Result**✗ Failed****Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear tyre perishing on sidewalls**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #11**

2015-08-27 10:21

MOT test number

109429252143

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10**

2015-08-25 07:56

MOT test number

408146989373

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

**MOT #9** 2013-03-15 09:56**MOT test number** 118884473020**Result** ✓ Passed**Notice** Nearside front and rear tyres slightly wearing out of shape**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-03-03 12:10**MOT test number** 845803062044**Result** ✓ Passed**Notice** Front brake discs worn**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2012-03-03 12:10**MOT test number** 335913162056**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Front brake discs worn**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2011-03-12 11:55**MOT test number** 805391971089**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2011-03-12 09:44**MOT test number** 707721071020**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2010-03-08 14:49**MOT test number** 344157060004**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #3** 2009-03-12 17:28**MOT test number** 612991679000**Result** ✓ Passed**MOT #2** 2008-11-06 14:19**MOT test number** 610691018381**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2008-11-06 14:19
MOT test number	421901018482
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-08-27
Last registration	2020-09-15
Complete history	See info



Registration #1	2005-08-27	25 mi
Registration #2	2008-11-06	28.720 mi
Registration #3	2009-03-12	29.022 mi
Registration #4	2010-03-08	37.569 mi
Registration #5	2011-03-12	46.010 mi
Registration #6	2011-03-12	46.010 mi
Registration #7	2012-03-03	50.660 mi
Registration #8	2013-03-15	60.211 mi
Registration #9	2015-08-25	72.212 mi
Registration #10	2015-08-27	72.220 mi
Registration #11	2016-03-20	75.377 mi
Registration #12	2016-03-20	75.377 mi
Registration #13	2016-03-20	75.377 mi
Registration #14	2016-03-20	75.377 mi
Registration #15	2016-03-20	75.377 mi
Registration #16	2016-03-20	75.377 mi
Registration #17	2016-03-20	75.377 mi
Registration #18	2016-03-20	75.377 mi
Registration #19	2016-03-20	75.377 mi

More info >



Dimensions & weight

Width	1724 mm
Height	1796 mm
Length	4137 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	2
Engine number	DXFR6119148