





report date: 2024-03-28

General information

Make	AUDI
Model	A1 TDI S LINE
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-27
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13





MOT history

MOT expiry date	2024-05-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	8

MOT #14	2024-04-26 08:55
MOT test number	961430745096
Result	X Failed
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Fail Offside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Fail Offside Headlamp aim too high (4.1.2 (a))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13		2023-05-04 10:58
MOT test	number	387280822655
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2022-09-27 12:15

MOT test number 337424921229

Result ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11 2022-09-27 08:33

MOT test number 925652814592

Result × Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Front Headlamp aim too low both (4.1.2 (a))

Fail
Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #10 2021-10-23 09:46

MOT test number 722216621427

Result / Passed

Advice Nearside Front Play in steering rack inner joint(s) slight

MOT #9 2020-10-21 12:20

MOT test number 922370712331

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8 2019-11-18 10:04

MOT test number 269750700862

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #7 2018-11-29 11:01

MOT test number 154910944704

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2017-12-01 12:11

MOT test number 249840447729

Result ✓ Passed

MOT #5 2016-12-01 13:29

MOT test number 743358556231

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-11-30 16:45

MOT test number 371497860595

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Headlights adjusted on test

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3 2015-11-13 13:33 **MOT test number** 155785163078 ✓ Passed Result MOT #2 2014-11-24 13:26 **MOT test number** 285798124350 Result ✓ Passed MOT #1 2013-11-18 12:52 748552123395 **MOT test number** Result ✓ Passed

CarCheck.co.uk page 6/13





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	3 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

*		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-30
Last registration	2024-04-26
Complete history	See info



Registration #1	2010-11-30	28 mi
Registration #2	2013-11-18	27.002 mi
Registration #3	2014-11-24	36.241 mi
Registration #4	2015-11-13	47.489 mi
Registration #5	2016-11-30	59.528 mi
Registration #6	2016-12-01	59.552 mi
Registration #7	2017-12-01	70.645 mi
Registration #8	2018-11-29	79.457 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

CAY980229