





General information

Make	ΤΟΥΟΤΑ
Model	LANDCRUISER ESTATE D-4D LC4
Colour	Grey
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	171 BHP
Max. torque	410 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	К





Internet history	
Entry 1	
Date	2021-06-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	6

MOT #14	2024-04-11 11:08
MOT test number	387470587344
Result	✓ Passed
Next expiry date	2025-04-10

MOT #2	13	2024-04-10 11:55
MOT te	st number	395169506484
Result		🗙 Failed
Fail	Windscreen washer not working (3.5 (a))	
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Fail	Nearside Parking brake inoperative on one side low figures (1.4.1 (a))	





MOT #12	2023-04-04 12:05
MOT test number	730673194242
Result	✓ Passed
Advice Rear Tyre has a cut but not deep enough to reach the ply or cords both side	des (5.2.3 (d) (i))
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d)	(ii))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #11	2022-04-02 09:04
MOT test number	768147773341
Result	✓ Passed
Advice Guards fitted to underside and outer sills	

MOT #10	2021-05-20 11:48
MOT test number	723092953390
Result	✓ Passed

MOT #9		2020-09-15 15:37
MOT test	number	402637754084
Result		✓ Passed
Advice	Water in o/s/f foglight	
Advice	Rear Brake hose has slight corrosion to ferrule both pipes at rear axle (1.1.12	2 (f) (i))
Advice (a) (i))	Front Outer Anti-roll bar pin or bush worn but not resulting in excessive move	ement bushes (5.3.4
Advice	Undertrays fitted unable to check certain items	
Advice	Steering column top bearing slightly worn (2.2.2 (b))	
Advice o/s (1.1.11	Rear Brake pipe corroded, covered in grease or other material front to rear a l (c))	t rear axle to n/s &



RF60F0U report date: 2024-03-28

MOT #8	2019-09-25 08:00
MOT test number	287419322163
Result	✓ Passed
AdviceNearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceNearside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #7	2018-09-24 10:45
MOT test number	220678131617
Result	🗸 Passed
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2017-09-23 08:10
MOT test number	979076652948
Result	✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle within	n zone 'A' (8.3.1a)

MOT #5 20	17-09-21 10:02
MOT test number	603012042587
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Front Front wheel bearing has excessive play (2.5.A.3c)	
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	

MOT #4	201	6-09-28 10:45
MOT test	number 2	29091448986
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	



RF60F0U
report date: 2024-03-28

MOT #3	2015-09-21 08:44
MOT test number	551200730515
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	
MOT #2	2014-09-22 15:41
MOT test number	538145364229
Result	✓ Passed
MOT #1	2013-09-26 11:16
MOT test number	555079263275
Result	✓ Passed



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 September 2024	Expires: 10 April 2025
Tax status	Valid until 1 September
Days left	126
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



RF60F0U report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-14
Last registration	2024-04-11
Complete history	See info



Registration #1	2010-10-14	14 mi
Registration #2	2013-09-26	49.504 mi
Registration #3	2014-09-22	65.609 mi
Registration #4	2015-09-21	83.908 mi
Registration #5	2016-09-28	100.932 mi
Registration #6	2017-09-21	119.170 mi
Registration #7	2017-09-23	119.172 mi
Registration #8	2018-09-24	137.547 mi
Registration #9		11.777 mi
Registration #9 Registration #10		10.000 est
-		01.000 est 01.000 est 01.000 est
Registration #10		01.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est 00.000 est
Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1885 mm
Height	1890 mm
Length	4760 mm
Wheel base	2790 mm
Kerb weight	2400 kg
Max. allowed weight	2990 kg
Additional information	
Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles	2
Engine number	1KD1974349