



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA DYNAMIQUE TOMTOM DCI FAP
Colour	Black
Year of manufacture	2011
Top speed	131 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-06-04
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2023-09-01
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	29
Total items failed	12

MOT #15 2022-09-02 10:42

MOT test number 510488870423

Result ✓ Passed

Next expiry date 2023-09-01

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14 2020-07-16 10:20

MOT test number 853685208328

Result ✓ Passed

MOT #13 2020-07-15 15:39

MOT test number 629092277552

Result ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Fail** Nearside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

**MOT #12** 2019-08-20 16:20**MOT test number** 958779775732**Result** ✓ Passed**MOT #11** 2019-08-19 15:42**MOT test number** 803019976364**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-09-18 14:10**MOT test number** 841991946801**Result** ✓ Passed**MOT #9** 2018-09-11 09:31**MOT test number** 271088643151**Result** ✗ Failed**Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #8** 2017-08-11 08:44**MOT test number** 533401953072**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Rear axle brakes 28% inbalance**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Under trays and engine covers fitted

**MOT #7**

2017-08-08 08:25

MOT test number

393902213259

Result**✗ Failed**

- Advice** Rear axle brakes 28% inbalance
- Advice** Nearside Rear Nail in tyre
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Under trays and engine covers fitted
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #6

2016-08-10 15:10

MOT test number

438421724456

Result**✓ Passed**

- Advice** Oil leak
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Engine bay covers and under body guards fitted
- Advice** Offside Front Tyre worn close to the legal limit 2mm bald on edges (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** X1 high vis stop light bulb not working
- Advice** Nearside Front Tyre worn close to the legal limit 2mm bald on edges (4.1.E.1)

**MOT #5** 2016-08-04 11:33**MOT test number** 128141873717**Result** ✗ Failed**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc small clip (2.5.C.1a)**Advice** Engine bay covers and under body guards fitted**Advice** Oil leak**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit 2mm bald on edges (4.1.E.1)**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** X1 high vis stop light bulb not working**Fail** Front brake application uneven (3.7.B.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 2mm bald on edges (4.1.E.1)**MOT #4** 2015-07-10 11:01**MOT test number** 625311795119**Result** ✓ Passed**MOT #3** 2014-07-15 12:53**MOT test number** 295216894190**Result** ✓ Passed**MOT #2** 2014-01-20 15:59**MOT test number** 118210124015**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-01-20 15:59
MOT test number	326500724094
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✕
Untaxed

Tax expired:
27 November 2022

✕
MOT

Expired:
1 September 2023

Tax status	Expired at 27 November 2022
Days left	519 days too late
MOT expiry date	1 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-25
Last registration	2022-09-02
Complete history	See info



Registration #1	2011-01-25	28 mi
Registration #2	2014-01-20	69.776 mi
Registration #3	2014-07-15	77.137 mi
Registration #4	2015-07-10	82.750 mi
Registration #5	2016-08-04	88.098 mi
Registration #6	2016-08-10	88.199 mi
Registration #7	2017-08-08	93.274 mi
Registration #8	2017-08-11	93.337 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1812 mm
Height	1398 mm
Length	4643 mm
Wheel base	2693 mm
Kerb weight	1486 kg
Max. allowed weight	1972 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	C012150