



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 270 CDI
Colour	Silver
Year of manufacture	2002
Top speed	115 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	370 Nm at 1.600 rpm
Engine capacity	2.688 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	35.3 mpg
Consumption combined	29.7 mpg
CO2 emission	250 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-09-21
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-08-22
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	24
Total items failed	12

MOT #21	2021-08-23 17:37
MOT test number	797767691069
Result	✓ Passed
Next expiry date	2022-08-22

MOT #20	2021-02-08 11:47
MOT test number	533531164102
Result	✓ Passed

MOT #19	2020-01-27 17:40
MOT test number	105648088149
Result	✓ Passed

MOT #18	2019-02-06 18:33
MOT test number	472703941731
Result	✓ Passed

Advice Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #17**

2019-02-05 17:11

MOT test number

311919497996

Result**✗ Failed****Fail** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively O/S,N/S (3.4 (b) (ii))**Fail** Offside Rear Lower Coil spring fractured or broken (5.3.1 (b) (i))**MOT #16**

2018-01-27 18:30

MOT test number

493530367918

Result**✓ Passed****Advice** Not able to see rear inner brake pad wear**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**Advice** Rear Outer Brake pad(s) wearing thin (3.5.1g)**Advice** Headlamp deteriorated but light output not reduced O/S,N/S (1.7.5a)**MOT #15**

2017-02-11 17:58

MOT test number

344392528550

Result**✓ Passed****Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #14** 2016-01-23 16:05**MOT test number** 792879012249**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Obligatory mirror deteriorated, but not seriously affecting the rear view (8.1.2a)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #13** 2015-02-14 14:12**MOT test number** 797565445051**Result** ✓ Passed**MOT #12** 2015-02-07 15:52**MOT test number** 197778735455**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #11** 2014-02-17 15:41**MOT test number** 728228644038**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #10** 2013-02-11 14:11**MOT test number** 148822243068**Result** ✓ Passed

**MOT #9** 2012-02-21 10:21**MOT test number** 746422352098**Result** ✓ Passed**MOT #8** 2011-02-05 11:37**MOT test number** 516156931076**Result** ✓ Passed**MOT #7** 2010-02-18 13:07**MOT test number** 880849540059**Result** ✓ Passed**Advice** Brake master cylinder fluid close to minimum level (3.6.G.1e)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2009-02-19 11:02**MOT test number** 811340859074**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2008-02-22 11:51**MOT test number** 523423358034**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2008-02-22 11:51**MOT test number** 184513058407**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.5c)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2007-02-03 16:40**MOT test number** 411484437099**Result** ✓ Passed**Advice** Exhaust emits black smoke during acceleration (7.3.A.2c)**MOT #2** 2006-02-16 16:34**MOT test number** 240477146052**Result** ✓ Passed**MOT #1** 2006-02-16 16:34**MOT test number** 381657846091**Result** ✗ Failed**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)



Tax & MOT check

✕
Untaxed

Tax expired:
24 May 2022

✕
MOT

Expired:
22 August 2022

Tax status	Expired at 24 May 2022
Days left	705 days too late
MOT expiry date	22 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	DN51XKX
Plate since	2019-06-29
Current registration	DN51XKX
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2002-01-18
Last registration	2021-08-23
Complete history	See info



Registration #1	2002-01-18	18 mi
Registration #2	2006-02-16	75.492 mi
Registration #3	2007-02-03	81.469 mi
Registration #4	2008-02-22	86.170 mi
Registration #5	2009-02-19	89.473 mi
Registration #6	2010-02-18	93.176 mi
Registration #7	2011-02-05	94.723 mi
Registration #8	2012-02-21	97.665 mi
Registration #9	2013-02-11	99.245 mi
Registration #10	2014-02-17	101.390 mi
Registration #11	2015-02-22	103.535 mi
Registration #12	2016-02-22	105.680 mi
Registration #13	2017-02-22	107.825 mi
Registration #14	2018-02-22	109.970 mi
Registration #15	2019-02-22	112.115 mi
Registration #16	2020-02-22	114.260 mi
Registration #17	2021-02-22	116.405 mi
Registration #18	2021-08-23	118.550 mi
Registration #19	2021-08-23	118.550 mi

More info >



Dimensions & weight

Width	2190 mm
Height	1820 mm
Length	4710 mm
Wheel base	2820 mm
Kerb weight	2115 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	61296330215624