





report date: 2024-03-29

## General information

Make	FIAT
Model	DOBLO 8V DYNAMIC H/R
Colour	Red
Year of manufacture	2009
Top speed	90 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



# Internet history

-	٠	B43.4	,	1
ш	L	ΙV		ж,

ciitiy 1	
Date	2021-01-29
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-26
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	11
Total items failed	3

MOT #16	2024-01-17 16:29
MOT test number	943751840982
Result	✓ Passed
Next expiry date	2025-01-26

MOT #15		2024-01-11 10:31
MOT test	number	310822623281
Result		<b>×</b> Failed
MAJOR	Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	
MAJOR	Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	

MOT #14	2023-01-16 11:48
MOT test number	340001790570
Result	✓ Passed

MOT #13		2022-01-27 14:00
MOT test	number	546979093301
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #12 2020-11-16 15:34

MOT test number 813218251137

**MOT #11** 2020-11-11 11:09

**MOT test number** 213866230214

Result X Failed

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #10 2019-10-16 14:18

**MOT test number** 906697154364

**Advice** Corrosion to front brake discs

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2018-10-10 15:11

MOT test number 941863270390

Result 

Passed

MOT #8 2017-10-09 15:08

**MOT test number** 756456883912

MOT #7 2016-10-13 14:38

**MOT test number** 896233624658

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



MOT #6 2015-10-07 09:57

**MOT test number** 720816677790

**MOT #5** 2015-10-07 09:57

**MOT test number** 713134932278

Result X Failed

**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2014-10-06 11:06

**MOT test number** 138669074231

**Result** ✓ Passed

MOT #3 2013-10-02 13:14

MOT test number 139425673291

Result 

Passed

**Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)

**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)

MOT #2 2012-10-18 12:09

**MOT test number** 355712992269

**Result** ✓ Passed

MOT #1 2012-10-18 12:09

**MOT test number** 145012692259

**Result** X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	26 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when moterly	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
STATE OF THE PARTY	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-07
Last registration	2024-01-17
Complete history	See info



Registration #1	2009-10-07	18 mi
Registration #2	2012-10-18	4.682 mi
Registration #3	2013-10-02	7.846 mi
Registration #4	2014-10-06	11.010 mi
Registration #5	2015-10-07	12.995 mi
Registration #6	2015-10-07	12.995 mi
Registration #7	2016-10-13	14.037 mi
Registration #8	2017-10-09	14.774 mi
Registration #9	2018-10-10	15.076 mi
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.117 es
Registration #13		11.777 au
Registration #14		11.777 mg
Registration #14 Registration #15		11.777 es
_		11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	1830 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

**Engine number** 5038149