



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2007
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	130 g/km
CO2 label	D





MOT history

MOT expiry date	2021-11-24
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	46
Total items failed	12

MOT #18	2020-11-25 11:39
MOT test number	505919974081
Result	✓ Passed
Next expiry date	2021-11-24
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #17	2019-05-25 08:41
MOT test number	272407772024
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #16	2019-05-24 13:40
MOT test number	933278332868
Result	✗ Failed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #15**

2018-05-23 12:49

MOT test number

599984865681

Result

✓ Passed

- Advice** Damage to body
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Damage to wheel trims
- Advice** Nearside Front Tyre worn close to the legal limit just on 1.6mm at time of test (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit worn on edges (4.1.E.1)

MOT #14

2018-05-09 09:46

MOT test number

213876474644

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit worn on edges (4.1.E.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Brake back plate(s) securing device excessively deteriorated (3.5.1j)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Windscreen wiper does not clear the windscreen effectively both sides (8.2.2)
- Advice** Damage to wheel trims
- Fail** Nearside Front Headlamp aim too high (1.8)
- Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Advice** Nearside Front Tyre worn close to the legal limit just on 1.6mm at time of test (4.1.E.1)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Damage to body



MOT #13

2017-05-20 09:41

MOT test number

209069011192

Result

✓ Passed

- Advice

Slight oil leak
- Advice

N/s/f c.v boot cracked
- Advice

O/s/r brake pipe corroded
- Advice

N/s/r tyre cracked
- Advice

Sump corroded
- Advice

O/s/f c.v boot cracked
- Advice

Both front tyres starting to crack
- Advice

O/s/r tyre worn on inner and outer edge and cracked

MOT #12

2017-05-20 09:41

MOT test number

370495186870

Result

✗ Failed

- Advice

O/s/f c.v boot cracked
- Advice

Both front tyres starting to crack
- Advice

O/s/r tyre worn on inner and outer edge and cracked
- Pass with rectification

Offside Stop lamp not working (1.2.1b)
- Advice

Slight oil leak
- Advice

N/s/f c.v boot cracked
- Advice

O/s/r brake pipe corroded
- Advice

N/s/r tyre cracked
- Advice

Sump corroded

**MOT #11** 2016-04-14 08:47**MOT test number** 841884194445**Result** ✓ Passed

- Advice** Near side front tyre wearing on inner edge
- Advice** Both rear tyres perished
- Advice** Nearside front tyre has cut in outer sidewall but not exposing cords

MOT #10 2016-04-14 08:47**MOT test number** 251532988885**Result** ✗ Failed

- Advice** Nearside front tyre has cut in outer sidewall but not exposing cords
- Advice** Near side front tyre wearing on inner edge
- Advice** Both rear tyres perished
- Pass with rectification** Rear registration plate insecure (6.3.1b)

MOT #9 2015-04-09 13:16**MOT test number** 216909895074**Result** ✓ Passed**MOT #8** 2014-07-15 09:19**MOT test number** 186676694180**Result** ✓ Passed

- Notice** Nearside rear tyre has been "run flat", damaged sidewall

**MOT #7** 2014-07-14 14:52**MOT test number** 619085994188**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear tyre has been "run flat", damaged sidewall**MOT #6** 2013-07-22 11:23**MOT test number** 268933503252**Result** ✓ Passed**MOT #5** 2012-07-14 11:24**MOT test number** 726246092170**Result** ✓ Passed**MOT #4** 2011-08-01 14:22**MOT test number** 585923411286**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2011-08-01 14:22**MOT test number** 627003611211**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)



MOT #2	2010-08-19 16:55
MOT test number	344241930420
Result	✓ Passed

MOT #1	2010-08-19 16:55
MOT test number	402231730206
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2020

✕
MOT

Expired:
24 November 2021

Tax status	Expired at 31 December 2020
Days left	1214 days too late
MOT expiry date	24 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-28
Current registration	XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-01
Last registration	2020-11-25
Complete history	See info



Registration #1	2007-09-01	25 mi
Registration #2	2010-08-19	25.140 mi
Registration #3	2011-08-01	32.895 mi
Registration #4	2012-07-14	41.675 mi
Registration #5	2013-07-22	47.189 mi
Registration #6	2014-07-14	54.691 mi
Registration #7	2014-07-15	54.691 mi
Registration #8	2015-04-09	59.063 mi
Registration #9	2016-04-14	64.958 mi
Registration #10	2016-04-14	64.958 mi
Registration #11	2016-04-14	64.958 mi
Registration #12	2016-04-14	64.958 mi
Registration #13	2016-04-14	64.958 mi
Registration #14	2016-04-14	64.958 mi
Registration #15	2016-04-14	64.958 mi
Registration #16	2016-04-14	64.958 mi
Registration #17	2016-04-14	64.958 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG7289668