





report date: 2024-03-29

General information

Make	FIAT
Model	FIORINO 16V MULTIJET
Colour	Silver
Year of manufacture	2014
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-06

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-18
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	24
Total items failed	0

MOT #11	2024-03-19 12:43
MOT test number	944574527179
Result	✓ Passed
Next expiry date 2025-03-18	
Minor Offside Windscreen damaged but not adversely affecting driver's view scratched (3.2 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened corr	roded (1.1.14 (a) (ii))

MOT #10		2022-07-06 09:58
MOT test	number	173665218115
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2021-07-08 12:21
MOT test number	245910551594
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2021-07-08 08:23

MOT test number 712608564681

Result X Failed

MAJOR Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MAJOR Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

MOT #7 2020-11-24 11:48

MOT test number 202221819245

Result \(\sqrt{Passed} \)

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #6 2020-11-24 09:48

MOT test number 752518348340

Result X Failed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2019-12-03 11:29

MOT test number 116443765209

Result

Passed

Advice Exhaust tailpipe clamp corroded and damaged but still secure and not leaking

Advice Offside Rear Tyre worn close to legal limit/worn on edge 185/55/15/88h on 3mm (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Play in steering rack inner joint(s)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

Passed

MOT test number

Sesult

Advice Offside Front Play in steering rack inner joint(s)

MAJOR Nearside Windscreen wiper not working (3.4 (a))

Advice Exhaust tailpipe clamp corroded and damaged but still secure and not leaking

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #3

MOT test number

831206369480

Result

✓ Passed

MOT #2 2018-11-26 15:23

MOT test number 655013121611

Result X Failed

MAJOR Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Result

MOT #1 2017-11-28 17:09
MOT test number 971784286220

Advice Power steering pipe(s) or hose(s) has slight seepage to cooler (2.3.3b)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check

Tax expired: 13 May 2023





Expires: 18 March 2025

Tax status	Expired at 13 May 2023
Days left	352 days too late
MOT expiry date	18 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
O WILCI	,

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	******
Current registration	NIE AND INC.
Flate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



CX64ENM report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-12-12
Last registration	2024-03-19
Complete history	See info



Registration #1	2014-12-12	24 mi
Registration #2	2017-11-28	35.860 mi
Registration #3	2018-11-26	48.221 mi
Registration #4	2018-11-29	48.221 mi
Registration #5	2019-12-03	60.623 mi
Registration #6	2019-12-03	60.623 mi
Registration #7	2020-11-24	68.780 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.77 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	5391568

CarCheck.co.uk page 12/12