



report date: 2024-03-29

General information

Make	FORD
Model	KUGA LX TDCI
Colour	White
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-01
Pictures	5
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-02
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	15
Total items failed	1

MOT #18	2024-01-31 14:06
MOT test number	133527834576
Result	✓ Passed
Next expiry date	2025-02-02

MOT #17	2023-01-26 13:25
MOT test number	213509577221
Result	✓ Passed

MOT #16	2022-01-31 12:01
MOT test number	756238333367
Result	✓ Passed

MOT #15	2021-02-03 11:10
MOT test number	354201256981
Result	✓ Passed

**MOT #14** 2020-10-20 15:36**MOT test number** 121280207793**Result** ✓ Passed

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Rear rear axle and suspension components corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #13 2020-10-20 10:50**MOT test number** 239504268144**Result** ✗ Failed

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear rear axle and suspension components corroded

MOT #12 2019-10-12 12:16**MOT test number** 756112808518**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front and rear corroded, offside rear inner face worst (1.1.14 (a) (ii))

MOT #11 2018-10-23 17:16**MOT test number** 388030349820**Result** ✓ Passed



MOT #10	2018-05-29 09:39
----------------	------------------

MOT test number	143958801960
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2017-05-23 16:21
---------------	------------------

MOT test number	382174457883
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2016-05-27 15:16
---------------	------------------

MOT test number	196512865126
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2015-06-04 16:35
---------------	------------------

MOT test number	896025955197
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-06-04 16:35
---------------	------------------

MOT test number	688515655151
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Front Registration plate lamp not working (1.1.C.1d)
--------------------------------	--

MOT #5	2015-01-13 16:56
---------------	------------------

MOT test number	829263115085
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-01-28 10:38
---------------	------------------

MOT test number	236948424000
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2013-01-18 10:33
MOT test number	588638413068
Result	✓ Passed

MOT #2	2012-02-06 16:03
MOT test number	525817132000
Result	✓ Passed

MOT #1	2011-10-14 10:25
MOT test number	488637781235
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FG58YZZ
Plate since	2019-03-29
Current registration	FG58YZZ
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-29
Last registration	2024-01-31
Complete history	See info



Registration #1	2008-10-29	19 mi
Registration #2	2011-10-14	22.932 mi
Registration #3	2012-02-06	25.364 mi
Registration #4	2013-01-18	31.086 mi
Registration #5	2014-01-28	38.513 mi
Registration #6	2015-01-13	44.378 mi
Registration #7	2015-06-04	46.964 mi
Registration #8	2016-05-27	57.582 mi
Registration #9	2017-05-23	69.270 mi
Registration #10	2018-05-29	78.991 mi
Registration #11	2019-05-29	88.712 mi
Registration #12	2020-05-29	98.433 mi
Registration #13	2021-05-29	108.154 mi
Registration #14	2022-05-29	117.875 mi
Registration #15	2023-05-29	127.596 mi
Registration #16	2024-01-31	137.317 mi
Registration #17	2024-01-31	147.038 mi
Registration #18	2024-01-31	156.759 mi
Registration #19	2024-01-31	166.480 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R41969