





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date	2021-07-10
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk

Entry 1

Date	2021-06-14	
Pictures	7	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #9		2024-03-16 08:22
MOT test	number	516047252367
Result		✓ Passed
Next expi	ry date	2025-03-20
Advice	Coolant leak	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Front Tyre worn close to legal limit/worn on edge offside and nearside (5.2	.3 (e))
Advice	Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Rear bumper strengthener bar damaged	
Advice	Nearside Front Lower Steering linkage ball joint has slight play (2.1.3 (b) (i))

MOT #8		2023-03-21 09:46
MOT test	number	119040396371
Result		✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Front Registration number plat cracked

Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

Advice Boot lid damage

Advice Offside Rear registration number plat light not working

MOT #6 2022-10-17 12:25 **MOT** test number 892230991566 Result × Failed **Advice** Offside Rear registration number plat light not working Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Advice Front Registration number plat cracked Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii)) Pass with rectification Rear Reversing lamp inoperative (4.6.1 (a)) **Advice** Boot lid damage

MOT #5

MOT test number

879230346947

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))

 MOT #4
 2020-09-29 14:57

 MOT test number
 485143868908

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2020-09-29 11:33

MOT test number 851948391037

Result X Failed

Fail Road wheel more than one fixing missing nearside front, offside front, nearside rear (5.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #2 2019-09-23 08:36

MOT test number 135001098674

Result \rightarrow Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn bald on edges (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn bald on edges (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2018-09-21 12:27

MOT test number 411913612031

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

ober of plates

faste since

MK65RGZ

report date: 2024-03-29

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FIAT had different number plates.

ur _____

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-23
Last registration	2024-03-16
Complete history	See info



Registration #1	2015-09-23	15 mi
Registration #2	2018-09-21	15.681 mi
Registration #3	2019-09-23	23.032 mi
Registration #4	2020-09-29	24.319 mi
Registration #5	2020-09-29	24.319 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 1121042