






report date: 2024-03-28

### General information

Make	CITROEN
Model	C1 FEEL ETG
Colour	Red
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	71 BHP
Max. torque	93 Nm at 4.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	2.8 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/11



### Internet history

### Entry 5

Date 2021-07-12

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 4

Date	2021-06-25
Date	2021 00 25

Pictures 25

Listing price <u>View report</u>









source: heycar.co.uk

Entry 3

Date 2021-06-25


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 2

Date	2021-06-23
------	------------

Pictures 12 page 2/11

## Listing price

### View report









source: cargurus.co.uk

#### Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #6		2024-03-28 10:34
MOT test	number	526909223404
Result		<b>✓</b> Passed
Next expi	ry date	2025-04-25
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear light damaged	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2023-04-12 13:21
MOT test	number 219169081973
Result	✓ Passed
Advice	Nearside Rear light lens damaged
Advice	Rear Tyre slightly damaged/cracking or perishing cracking in tread. both sides (5.2.3 (d) (ii))

MOT #4	2023-04-12 08:59
MOT test number	184469782096
Result	<b>X</b> Failed
Advice Rear Tyre slightly damaged/cracking or perishing cracking in tread. both sides (5.2.3 (d) (ii))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Nearside Rear light lens damaged	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2022-04-26 09:57 **MOT** test number 748243118123 Result × Failed Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Pass with rectification** Offside Headlamp aim too high (4.1.2 (a)) **Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #1

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN		
have? Check it in the premium report and see all owner registrations. Download the full r	eport <u>nere</u> .	
HARMAN		
***************************************		
***************************************		
**********		
***************************************		
*************		
	More info >	
Plate changes		
See in this check if this CITROEN had different number plates.		
See in this check if this errively had different number plates.		
Number of prates		
Current registration	NE NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	
	More iiiio >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-03-29
Last registration	2024-03-28
Complete history	See info



Registration #1	2018-03-29	24 mi
Registration #2	2021-03-19	13.171 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		77.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



# Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	860 kg
Max. allowed weight	1240 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	8590963

CarCheck.co.uk page 11/11