



VXI4YPL

report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H LUXURY
Colour	Black
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	178 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.493 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-09-06
Pictures	46
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-27
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #9	2024-02-24 13:30
MOT test number	968191394440
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-02-21 14:12
MOT test number	956314401704
Result	✓ Passed
Advice	Emission Too Clean
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2022-02-07 14:34
MOT test number	644399032136
Result	✓ Passed
Advice	Low emission

**MOT #6** 2021-02-20 09:43**MOT test number** 362658212407**Result** ✓ Passed**MOT #5** 2020-02-15 11:03**MOT test number** 298805872731**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2019-02-28 16:53**MOT test number** 968666892813**Result** ✓ Passed**MOT #3** 2018-03-27 10:48**MOT test number** 391797249551**Result** ✓ Passed**MOT #2** 2018-03-27 10:48**MOT test number** 319670695321**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #1** 2017-03-22 10:42**MOT test number** 286180992315**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 10,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	<b>VX14YPL</b>
Plate since	2014-03-28
Current registration	<b>VX14YPL</b>
Plate since	2014-03-28

More info >





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-29
Last registration	2024-02-24
Complete history	<a href="#">See info</a>



Registration #1	2014-03-29	21 mi
Registration #2	2017-03-22	37.830 mi
Registration #3	2018-03-27	46.197 mi
Registration #4	2018-03-27	46.197 mi
Registration #5	2019-02-28	51.876 mi
Registration #6	2020-02-15	56.605 mi
Registration #7	2020-02-28	56.605 mi
Registration #8	2020-02-28	56.605 mi
Registration #9	2020-02-28	56.605 mi
Registration #10	2020-02-28	56.605 mi
Registration #11	2020-02-28	56.605 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AR1005509