





report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D4 BUSINESS EDITION
Colour	Black
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



PX15LDZ

report date: 2024-03-28

Internet history

Entry 4

Date 2022-01-13

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 3

Date 2022-01-05

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-09-25

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

Entry 1

Date carcheck.co.uk 2021-09-24 page 2/12

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	4

MOT #10	2024-01-23 13:18
MOT test number	515998619216
Result	✓ Passed
Next expiry date	2025-01-23

MOT #9	2024-01-23 12:00
MOT test number	171869909024
Result	× Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

MOT #8		2023-01-18 15:02
MOT test	number	555820002074
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Offside Front Outer Tyre slightly damaged/cracking or perishing side walls (5.2.3	3 (d) (ii))

MOT #7	2022-01-24 17:17
MOT test number	362765251502
Result	✓ Passed

CarCheck.co.uk page 3/12



(e)

PX15LDZ report date: 2024-03-28

MOT #6 2021-03-01 12:17

MOT test number 207415602652

Result ✓ Passed

MOT #5 2020-02-16 12:56

MOT test number 499147308498

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3 mm and inner edge very worn (5.2.3

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #4 2019-03-02 11:42

MOT test number 470316376687

MOT #3 2019-03-01 17:30

MOT test number 319012611121

Result × Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2 2018-02-05 10:02

MOT test number 671799874884

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Both rear tyres have uneven wear on the inner edges


Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



PX15LDZ

report date: 2024-03-28



CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



PX15LDZ

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		7
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-03-03
Last registration	2024-01-23
Complete history	See info



Registration #1	2015-03-03	13 mi
Registration #2	2018-02-05	100.806 mi
Registration #3	2018-02-05	100.806 mi
Registration #4	2019-03-01	120.979 mi
Registration #5	2019-03-02	120.985 mi
Registration #6	2020-02-16	129.038 mi
Registration #7	2021-03-01	133.865 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1606 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12

Number of axles2Engine number1159399