



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI S/S
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.5 mpg
Consumption extra urban	61.3 mpg
Consumption combined	54.2 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-14
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-28
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	25
Total items failed	6

MOT #11	2023-08-29 13:19
MOT test number	215308334368
Result	✓ Passed
Next expiry date	2024-08-28

MOT #10	2023-08-29 13:19
MOT test number	308685606769
Result	✗ Failed
<b>Pass with rectification</b> Stop lamp(s) all not working (4.3.1 (a) (iii))	

MOT #9	2022-08-16 15:31
MOT test number	151726009748
Result	✓ Passed
<b>Advice</b> Exhaust rear box corroded	
<b>Advice</b> O/s headlight lens slightly deteriorated	
<b>Advice</b> Chip in screen	
<b>Advice</b> Both rear springs corroded	
<b>Advice</b> Under-trays fitted not allowing full underside inspection	

**MOT #8**

2022-08-12 14:16

**MOT test number**

172976097707

**Result****✗ Failed**

- Advice** Both front tyres worn 195 60 16c
- Advice** Chip in screen
- Advice** Both rear springs corroded
- Advice** Coolant leak
- Advice** Front brake discs very worn and corroded - O/S/F pads worn low
- Advice** Exhaust rear box corroded
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** O/s headlight lens slightly deteriorated
- Advice** Under-trays fitted not allowing full underside inspection

**MOT #7**

2021-08-10 15:46

**MOT test number**

866902587380

**Result****✓ Passed**

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6**

2021-08-09 13:34

**MOT test number**

620166485709

**Result****✗ Failed**

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Nail in tyre and cracking/perished
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #5** 2020-08-24 09:09**MOT test number** 326426726147**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords & nail in tread area (5.2.3 (d) (i))**MOT #4** 2020-08-21 08:56**MOT test number** 251079456223**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords & nail in tread area (5.2.3 (d) (i))**MOT #3** 2019-08-23 10:53**MOT test number** 461581648715**Result** ✓ Passed**Advice** Springs slightly corroded**Advice** Front discs slightly worn and corroded**MOT #2** 2018-08-20 08:26**MOT test number** 889334498505**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2017-08-24 14:57
MOT test number	642022916327
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
28 October 2023

✓

MOT

Expires:  
28 August 2024

Tax status	Expired at 28 October 2023
Days left	183 days too late
MOT expiry date	28 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LR14WYC</b>
Plate since	2024-03-29
Current registration	<b>LR14WYC</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-20
Last registration	2023-08-29
Complete history	<a href="#">See info</a>



Registration #1	2014-05-20	15 mi
Registration #2	2017-08-24	40.001 mi
Registration #3	2018-08-20	58.815 mi
Registration #4	2019-08-23	76.031 mi
Registration #5	2020-08-21	99.413 mi
Registration #6	2020-08-24	99.413 mi
Registration #7	2021-08-09	114.870 mi
Registration #8	2022-08-29	131.277 mi
Registration #9	2022-08-29	131.277 mi
Registration #10	2022-08-29	131.277 mi
Registration #11	2022-08-29	131.277 mi
Registration #12	2022-08-29	131.277 mi
Registration #13	2023-08-29	131.277 mi

More info >



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	198A30007170306 LJ5