



RENAULT

LMI4FTF


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A









Internet history

Entry 1

Date	2022-02-17
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-31
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	20
Total items failed	12

MOT #12	2024-01-30 13:24
MOT test number	190708817522
Result	✓ Passed
Next expiry date	2025-01-31

MOT #11	2023-01-30 14:28
MOT test number	280145073893
Result	✓ Passed

MOT #10	2022-02-01 12:17
MOT test number	890645191276
Result	✓ Passed

MOT #9	2021-05-28 13:05
MOT test number	231269703991
Result	✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** N/s side repeater damaged but sill working
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8**

2021-05-27 10:50

**MOT test number**

946864143487

**Result****✗ Failed**

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** N/s side repeater damaged but sill working
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm also punctured (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #7**

2020-06-03 11:58

**MOT test number**

687641925983

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))
- Advice** Nearside Front Nail in tyre
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.3mm (5.2.3 (e))

**MOT #6** 2020-05-27 11:10**MOT test number** 239161960663**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.3mm (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Nail in tyre**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #5** 2019-03-14 09:59**MOT test number** 474544715911**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**MOT #4** 2019-03-13 15:40**MOT test number** 920275130258**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**MOT #3** 2018-03-23 10:53**MOT test number** 788103688151**Result** ✓ Passed



MOT #2	2018-03-22 15:01
MOT test number	436167002357
Result	✗ Failed
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #1	2017-03-24 15:35
MOT test number	939402874747
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
31 January 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	31 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-29
Last registration	2024-01-30
Complete history	<a href="#">See info</a>



Registration #1	2014-03-29	10 mi
Registration #2	2017-03-24	23.229 mi
Registration #3	2018-03-22	40.803 mi
Registration #4	2018-03-23	40.804 mi
Registration #5	2019-03-13	58.512 mi
Registration #6	2019-03-14	58.512 mi
Registration #7	2020-05-27	76.602 mi
Registration #8	2020-05-27	76.602 mi
Registration #9	2020-05-27	76.602 mi
Registration #10	2020-05-27	76.602 mi
Registration #11	2020-05-27	76.602 mi
Registration #12	2020-05-27	76.602 mi
Registration #13	2020-05-27	76.602 mi
Registration #14	2020-05-27	76.602 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D510601