



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	Purple
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-05-05
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-22
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	21
Total items failed	4

MOT #8	2023-05-17 14:54
--------	------------------

MOT test number	994523826107
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-22
------------------	------------

- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Exhaust has a minor leak of exhaust gases flex pipe (6.1.2 (a))
- Advice

Front Service brake fluctuating, but not excessively nearside border line pass (1.2.1 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall and perishing (5.2.3 (d) (i))

**MOT #7**

2023-05-17 09:03

**MOT test number**

100741129160

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall and perishing (5.2.3 (d) (i))
- Fail** Nearside Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flex pipe (6.1.2 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Service brake fluctuating, but not excessively nearside border line pass (1.2.1 (e))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #6**

2022-05-23 09:55

**MOT test number**

883026990999

**Result****✓ Passed****MOT #5**

2021-08-27 13:57

**MOT test number**

193557368791

**Result****✓ Passed**

- Advice** Front Both lower arm rear bushes starting to perish

**MOT #4** 2021-08-27 07:56**MOT test number** 225075778090**Result** ✗ Failed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Front Both lower arm rear bushes starting to perish

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2020-09-11 15:15**MOT test number** 628283993350**Result** ✓ Passed**MOT #2** 2019-09-30 10:35**MOT test number** 559046397844**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #1** 2018-02-26 09:29**MOT test number** 510730938408**Result** ✓ Passed

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
22 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	22 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-25
Last registration	2023-05-17
Complete history	<a href="#">See info</a>



Registration #1	2015-03-25	24 mi
Registration #2	2018-02-26	19.352 mi
Registration #3	2019-09-30	30.162 mi
Registration #4	2020-09-11	37.395 mi
Registration #5	2021-08-27	37.681 mi
Registration #6	2022-05-20	38.277 mi
Registration #7	2022-05-20	38.277 mi
Registration #8	2022-05-20	38.277 mi
Registration #9	2022-05-20	38.277 mi
Registration #10	2023-05-17	38.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150067940