

Ford



General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel







MOT history

MOT expiry date	2025-01-18
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #16	2024-01-13 17:17
MOT test number	185699119719
Result	🗸 Passed
Next expiry date	2025-01-18
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Front Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #15	2023-01-10 12:10
MOT test number	437426429580
Result	✓ Passed
Advice Nearside Outer Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))	
Advice Offside Outer Integral body structure is deformed but structural rigidity reduced (6.1.1 (a) (i))	is not significantly

MOT #14	2022-01-13 19:08
MOT test number	770083822018
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	





MOT #13	2022-01-13 19:08
MOT test number	115803422525
Result	× Failed
Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #12	2021-01-19 14:02
MOT test number	517687901080
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #11	2019-10-12 12:01
MOT test number	827675272516
Result	✓ Passed
Minor Nearside Obligatory mirror slightly damaged glass is cracked (3.3 (b) (i))	

MOT #3	10	2019-10-09 16:00
MOT te	st number	459475361495
Result		🗙 Failed
Fail	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))	
Mino	Nearside Obligatory mirror slightly damaged glass is cracked (3.3 (b) (i))	





MOT 40	2010 10 12 10.41
MOT #9	2018-10-13 10:41
MOT test number	638432783817
Result	Passed
Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement mounting bushes (5.3.4 (a) (i))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
MOT #8	2017-10-13 09:55
MOT test number 406292342	
Result	Passed
MOT #7	2017-10-12 15:19
MOT test number	321380846755
Result	🗙 Failed
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front Suspension arm rubber bush deteriorated re (2.4.G.2)	esulting in excessive movement rear bush
Fail Central Stop lamp not working (1.2.1b)	
Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f))
1	

MOT #6	2016-10-12 07:35
MOT test number	849563438837
Result	Passed
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but movement rear bush (2.4.G.2)	not resulting in excessive





MOT #5		2015-10-16 09:02
MOT test number		385222989989
Result		✓ Passed
Advice Front Brake p	ad(s) wearing thin (3.5.1g)	
Advice Nearside from	t tyre centre tread worn close to wear indicators.	
Advice Rear Brake pa	ad(s) wearing thin (3.5.1g)	
Advice Front brake d	iscs worn.	
MOT #4		2014-08-07 11:32
MOT test number		819579214211
Result		✓ Passed
MOT #3		2013-08-07 09:05
MOT #3		258779913254
Result		✓ Passed
MOT #2		2013-08-07 09:05
MOT test number		468949713210
Result		🗙 Failed
Pass with rectification	n Offside Windscreen wiper does not clear the w	vindscreen effectively (8.2.2)
MOT #1		2012-08-29 10:26

MOT #1	2012-08-29 10:26
MOT test number	388132842496
Result	✓ Passed





Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 February 2025	Expires: 18 January 2025
Tax status	Valid until 1 February
Days left	277
MOT expiry date	18 January 2025
Full MOT history	See MOT history





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-22
Last registration	2024-01-13
Complete history	See info



Registration #1	2009-09-22	28 mi
Registration #2	2012-08-29	24.403 mi
Registration #3	2013-08-07	27.120 mi
Registration #4	2014-08-07	38.526 mi
Registration #5	2015-10-16	64.191 mi
Registration #6	2016-10-12	77.389 mi
Registration #7	2017-10-12	87.463 mi
Registration #8	2017-10-13	87.463 mi
Registration #9	10003-00-00	11.777 mi
-	00003-00-00 0000-00-00	11.227 est
Registration #9	0000.00.00 0000.00.00 0000.00.00	01.000 est 01.000 est 01.000 est
Registration #9 Registration #10	0000.00.00 0000.00.00 0000.00.00 0000.00.	00.000 est 01.000 est 00.000 est 01.000 est
Registration #9 Registration #10 Registration #11	10000-00-00 10000-00-00 10000-00-00 10000-00-00 10000-00-00	00.000 est 0.000 est 00.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11 Registration #12	1000 - 20 - 20 1000 - 20 - 20 1000 - 20 - 20 1000 - 20 - 20 1000 - 20 - 20	00.000 est 0.000 est 00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13	1000 20 20 1000 20 20	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420