



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	5
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-03
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	25
Total items failed	0

MOT #15	2024-03-04 14:38
MOT test number	294592861710
Result	✓ Passed
Next expiry date	2025-03-03

MOT #14	2023-07-24 09:07
MOT test number	588693593150
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #13**

2022-07-25 08:58

MOT test number

890242485921

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12

2021-07-16 14:41

MOT test number

199515324098

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11

2020-07-21 09:01

MOT test number

864982972476

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10** 2019-07-16 09:27**MOT test number** 882875238229**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2019-07-15 13:01**MOT test number** 392975015140**Result** ✗ Failed**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2018-07-21 16:14**MOT test number** 516181581563**Result** ✓ Passed**MOT #7** 2017-07-31 14:27**MOT test number** 140475999433**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a minor leak of exhaust gases rear silencer (7.1.2)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #6** 2017-05-13 07:54**MOT test number** 279770921710**Result** ✓ Passed



MOT #5	2016-05-21 08:40
---------------	------------------

MOT test number	204379990090
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #4	2015-05-23 10:31
---------------	------------------

MOT test number	209093545490
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-05-31 11:17
---------------	------------------

MOT test number	955231754186
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-05-18 09:25
---------------	------------------

MOT test number	819098533107
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-05-19 09:11
---------------	------------------

MOT test number	715430342119
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-26
Last registration	2024-03-04
Complete history	See info



Registration #1	2009-05-26	21 mi
Registration #2	2012-05-19	14.782 mi
Registration #3	2013-05-18	18.621 mi
Registration #4	2014-05-31	23.964 mi
Registration #5	2015-05-23	30.281 mi
Registration #6	2016-05-21	35.114 mi
Registration #7	2017-05-13	40.521 mi
Registration #8	2017-07-31	41.772 mi
Registration #9	2018-07-21	47.727 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5187434