




report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Black
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-18
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-04-30
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	4
Total items failed	16

MOT #15	2021-05-01 11:48
MOT test number	698911955360
Result	✓ Passed
Next expiry date	2022-04-30

MOT #14	2020-03-12 19:37
MOT test number	790077042248
Result	✓ Passed

MOT #13	2020-03-11 15:26
MOT test number	914667344325
Result	✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2019-07-23 12:06
MOT test number	532982756397
Result	✓ Passed

**MOT #11**

2019-07-18 10:27

MOT test number

212897176243

Result**✗ Failed**

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #10

2018-05-03 09:51

MOT test number

984773736374

Result**✓ Passed****MOT #9**

2017-05-19 13:40

MOT test number

756579765564

Result**✓ Passed****MOT #8**

2017-05-19 13:40

MOT test number

697091285713

Result**✗ Failed**

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2016-04-27 09:41**MOT test number** 119290404145**Result** ✓ Passed**MOT #6** 2015-05-08 14:44**MOT test number** 646178825126**Result** ✓ Passed**MOT #5** 2014-05-07 12:11**MOT test number** 145047124165**Result** ✓ Passed**MOT #4** 2014-05-07 12:11**MOT test number** 176247624164**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2013-05-14 09:33**MOT test number** 956734333164**Result** ✓ Passed**MOT #2** 2012-05-17 09:33**MOT test number** 357228032138**Result** ✓ Passed**Notice** Side wall of offside rear tyre damaged



MOT #1	2012-05-17 09:33
MOT test number	418238632184
Result	✗ Failed
<div>NoticeSide wall of offside rear tyre damaged</div> <div>Pass with rectificationOffside Headlamp aim beam image obviously incorrect (1.8.A.1b)</div>	



Tax & MOT check

×

Untaxed

Tax expired:
1 June 2022

×

MOT

Expired:
30 April 2022

Tax status

Expired at 1 June 2022

Days left

699 days too late

MOT expiry date

30 April 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-14
Last registration	2021-05-01
Complete history	See info



Registration #1	2009-07-14	6 mi
Registration #2	2012-05-17	48.749 mi
Registration #3	2013-05-14	59.698 mi
Registration #4	2014-05-07	71.337 mi
Registration #5	2015-05-08	83.017 mi
Registration #6	2016-04-27	95.833 mi
Registration #7	2017-05-19	110.190 mi
Registration #8	2017-05-19	110.190 mi
Registration #9	2019-05-01	110.190 mi
Registration #10	2019-05-01	110.190 mi
Registration #11	2019-05-01	110.190 mi
Registration #12	2019-05-01	110.190 mi
Registration #13	2019-05-01	110.190 mi
Registration #14	2019-05-01	110.190 mi
Registration #15	2019-05-01	110.190 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C73512