



report date: 2024-03-29

General information

Make	HONDA
Model	LOGO 8V
Colour	Blue
Year of manufacture	2000
Top speed	90 mph
0 - 60 mph	14.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	64 BHP
Max. torque	108 Nm at 2.500 rpm
Engine capacity	1.343 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2021-07-03
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-02
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-04
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	10
Total items failed	11

MOT #19	2024-01-05 15:29
MOT test number	408179687592
Result	✓ Passed
Next expiry date	2025-01-04

MOT #18	2023-12-14 14:21
MOT test number	905999897917
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Fail	Fuel cap/sealing device missing (6.1.3 (b) (i))
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #17	2022-12-23 08:21
MOT test number	318685783317
Result	✓ Passed

**MOT #16**

2022-09-05 08:47

MOT test number

933237498536

Result

✗ Failed

Fail

Rear Bumper insecure (6.1.4 (a) (i))

Fail

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail

Nearside Headlamp insecure (4.1.1 (c))

MOT #15

2021-09-23 15:58

MOT test number

875650408342

Result

✓ Passed

MOT #14

2018-11-07 08:39

MOT test number

334569696173

Result

✓ Passed

MOT #13

2016-02-17 15:02

MOT test number

571348779496

Result

✓ Passed

MOT #12

2014-10-17 14:26

MOT test number

296060794296

Result

✓ Passed

Advice

Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

Notice

Engine covers fitted obscuring some components in the engine bay

Notice

Under-trays fitted obscuring some underside components

**MOT #11** 2013-06-11 14:44**MOT test number** 157862463127**Result** ✓ Passed**MOT #10** 2012-06-19 09:08**MOT test number** 258261172165**Result** ✓ Passed**MOT #9** 2011-06-22 14:38**MOT test number** 486893571153**Result** ✓ Passed**MOT #8** 2011-06-22 14:38**MOT test number** 639813771113**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too far to the left (1.8)**Pass with rectification** Nearside Headlamp aim too low and too far to the right. (1.8)**MOT #7** 2010-06-22 13:10**MOT test number** 572413270104**Result** ✓ Passed**Notice** Both rear tyres cracking and perished on sidewalls**MOT #6** 2009-06-26 09:01**MOT test number** 140007479130**Result** ✓ Passed**MOT #5** 2008-06-25 14:39**MOT test number** 873577078196**Result** ✓ Passed

**MOT #4** 2007-06-25 14:41**MOT test number** 584736377116**Result** ✓ Passed**MOT #3** 2007-06-25 14:41**MOT test number** 773936377152**Result** ✗ Failed

- Pass with rectification** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Pass with rectification** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2006-07-17 10:29**MOT test number** 223558496125**Result** ✓ Passed

- Notice** Tyre side walls cracked

MOT #1 2005-07-28 11:09**MOT test number** 301869305441**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 December
-------------------	------------------------

Days left	215
------------------	-----

MOT expiry date	4 January 2025
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2000-08-26
Last registration	2024-01-05
Complete history	See info



Registration #1	2000-08-26	10 mi
Registration #2	2005-07-28	16.524 mi
Registration #3	2006-07-17	17.242 mi
Registration #4	2007-06-25	17.844 mi
Registration #5	2008-06-25	18.483 mi
Registration #6	2009-06-26	19.120 mi
Registration #7	2010-06-22	19.605 mi
Registration #8	2011-06-22	19.953 mi
Registration #9	2012-06-19	20.634 mi
Registration #10	2013-06-11	21.174 mi
Registration #11	2014-06-11	21.174 mi
Registration #12	2015-06-11	21.174 mi
Registration #13	2016-06-11	21.174 mi
Registration #14	2017-06-11	21.174 mi
Registration #15	2018-06-11	21.174 mi
Registration #16	2019-06-11	21.174 mi
Registration #17	2020-06-11	21.174 mi
Registration #18	2021-06-11	21.174 mi
Registration #19	2022-06-11	21.174 mi
Registration #20	2023-06-11	21.174 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1645 mm
Height	1524 mm
Length	3785 mm
Kerb weight	880 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	D13B71103774