



report date: 2024-03-29

General information

Make	VAUXHALL
Model	CASCADA SE CDTI S/S
Colour	Blue
Year of manufacture	2013
Top speed	135 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	165 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.956 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 3

Date	2023-03-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 2

Date	2022-11-14
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 1

Date	2022-02-05
Pictures	15
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2024-06-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #9	2023-06-19 08:44
MOT test number	413228581776
Result	✓ Passed
Next expiry date	2024-06-18

MOT #8	2023-06-13 11:51
MOT test number	529193536373
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Windscreen washer not working (3.5 (a))

MOT #7	2021-11-04 10:10
MOT test number	215570694937
Result	✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2020-10-29 10:17**MOT test number** 106183192502**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2019-05-03 12:08**MOT test number** 318002051774**Result** ✓ Passed**MOT #4** 2018-05-04 10:13**MOT test number** 121056734904**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2018-04-26 08:15**MOT test number** 151080921849**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Valve stem seriously damaged (4.1.D.1e)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Valve stem seriously damaged (4.1.D.1e)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2017-04-21 09:28**MOT test number** 461147916135**Result** ✓ Passed



MOT #1	2016-04-25 11:27
MOT test number	181085428133
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
18 June 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	18 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YX13OWA
Plate since	2019-03-29
Current registration	 YX13OWA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-29
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2013-04-29	10 mi
Registration #2	2016-04-25	37.976 mi
Registration #3	2017-04-21	48.865 mi
Registration #4	2018-04-26	62.110 mi
Registration #5	2018-05-04	62.187 mi
Registration #6	2019-05-03	70.744 mi
Registration #7	2020-10-29	80.311 mi
Registration #8	2021-05-20	91.277 mi
Registration #9	2022-05-20	101.277 mi
Registration #10	2023-05-20	111.277 mi
Registration #11	2023-05-20	121.277 mi
Registration #12	2023-05-20	131.277 mi
Registration #13	2023-05-20	141.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1741 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A20DTH -17B16492LBS