





report date: 2024-03-29

General information

| Make | BMW |
|---------------------|---------------------|
| Model | 3 SERIES 330E SPORT |
| Colour | Black |
| Year of manufacture | 2016 |
| Top speed | 140 mph |
| 0 - 60 mph | 6.1 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 181 BHP |
|----------------------|---------------------|
| Max. torque | 290 Nm at 4.250 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption combined | 148.7 mpg |
| CO2 emission | 45 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-06-03


Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-27 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #7 | 2023-10-19 09:00 |
|------------------|------------------|
| MOT test number | 853371503449 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-27 |

| MOT #6 | | 2022-10-28 15:27 |
|----------|---|------------------|
| MOT test | number | 448271356204 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Play in steering rack inner joint(s) | |

| MOT #5 | | 2022-06-09 08:51 |
|-----------------|---|------------------|
| MOT test number | er | 975201882893 |
| Result | | ✓ Passed |
| | | |
| MOT #4 | | 2022-06-08 14:07 |
| MOT test number | er | 690339609032 |
| Result | | × Failed |
| DANGEROUS | Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



MOT #3 2021-06-01 05:36

MOT test number 839689079618

Minor Offside Front Windscreen wiper blade defective smearing (3.4 (b) (i))

Minor Nearside Front Windscreen wiper blade defective smearing (3.4 (b) (i))

MOT #2 2020-06-29 12:20

MOT test number 645835291801

Result ✓ Passed

MOT #1 2019-05-14 08:21

MOT test number 454648461576

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Advise rear left tyre 3.5mm (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 186 |
| MOT expiry date | 27 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner mistory | | |
|---|-------------|--|
| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I | | |
| | | |
| ******** | | |
| *************************************** | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | | |
| *************************************** | | |
| | More info > | |
| Plate changes | | |
| See in this check if this BMW had different number plates. | | |
| Number of plates | | |
| Current registration | NK NE | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info > | |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



HK16UHL

report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-06-08 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| Registration #1 | 2016-06-08 | 27 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-05-14 | 20.306 mi |
| Registration #3 | 2020-06-29 | 27.275 mi |
| Registration #4 | 2021-06-01 | 35.694 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 84% |
| Pedestrian | 78% |
| Safety systems | 86% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 1811 mm |
|---------------------|---------|
| Height | 1429 mm |
| Length | 4633 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1660 kg |
| Max. allowed weight | 2195 kg |

Additional information

| | | • |
|-----------------------------------|------------------|------------|
| Fuel tank capacity | 41 | |
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 | page 11/11 |