



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Blue
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2025-04-07
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	27
Total items failed	5

MOT #13	2024-03-13 11:16
MOT test number	761209417113
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12	2024-03-13 11:16
MOT test number	461606639313
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #11**

2023-03-21 14:24

MOT test number

760867749057

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2023-03-21 14:24

MOT test number

424140327652

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Headlamps matched pair are not the same colour yellow out put (4.1.4 (d))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Pass with rectification** Offside Headlamps matched pair are not the same colour blue out put (4.1.4 (d))

MOT #9

2022-03-08 13:52

MOT test number

292012163220

Result

✓ Passed

MOT #8

2021-04-08 14:15

MOT test number

161505093275

Result

✓ Passed



MOT #7	2021-04-08 10:44
MOT test number	577984611004
Result	✗ Failed
MAJOR Offside Rear Road wheel fixing missing (5.2.1 (a) (i))	

MOT #6	2020-11-07 09:57
MOT test number	820830137596
Result	✓ Passed
Advice Items removed from driver's view prior to test	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))	
Minor Offside Front Electrical wiring inadequately secured (4.11 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))	

MOT #5	2020-11-07 09:57
MOT test number	560139498788
Result	✗ Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))	
Advice Items removed from driver's view prior to test	
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))	
Minor Offside Front Electrical wiring inadequately secured (4.11 (a) (i))	

MOT #4	2019-04-22 10:30
MOT test number	559996701193
Result	✓ Passed



MOT #3	2018-05-12 11:09
MOT test number	156212445899
Result	✓ Passed

MOT #2	2018-05-12 11:09
MOT test number	597489168939
Result	✗ Failed
<div>Pass with rectification</div> Front Headlamp aim beam image obviously incorrect both (1.8.A.1b)	

MOT #1	2017-05-06 11:59
MOT test number	758429001835
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
7 April 2025

Tax status	Valid until 1 May
Days left	368
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-06-30
Last registration	2024-03-13
Complete history	See info



Registration #1	2014-06-30	8 mi
Registration #2	2017-05-06	14.912 mi
Registration #3	2018-05-12	16.987 mi
Registration #4	2018-05-12	16.987 mi
Registration #5	2019-04-22	25.222 mi
Registration #6	2020-11-07	33.125 mi
Registration #7	2020-11-07	33.125 mi
Registration #8	2020-11-07	33.125 mi
Registration #9	2020-11-07	33.125 mi
Registration #10	2020-11-07	33.125 mi
Registration #11	2020-11-07	33.125 mi
Registration #12	2020-11-07	33.125 mi
Registration #13	2020-11-07	33.125 mi
Registration #14	2020-11-07	33.125 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073