



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	4

MOT #18	2024-02-27 13:01
MOT test number	922348599670
Result	✓ Passed
Next expiry date	2025-02-26

MOT #17	2022-11-04 14:09
MOT test number	162544370295
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #16	2021-11-02 12:49
MOT test number	201069988179
Result	✓ Passed

**MOT #15** 2021-10-29 11:04**MOT test number** 620379892024**Result** ✗ Failed

- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

MOT #14 2020-10-12 10:31**MOT test number** 263447973168**Result** ✓ Passed

- Advice** Offside Rear Shock absorbers has slight external damage to the casing very badly corroded (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing very badly corroded (5.3.2 (b))
- Advice** The exhaust system is badly corroded and in poor condition

**MOT #13**

2020-10-08 10:27

MOT test number

786453529973

Result

✗ Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing very badly corroded (5.3.2 (b))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** The exhaust system is badly corroded and in poor condition**MAJOR** Rear Exhaust silencer insecure exhaust clamp is missing (8.1.1 (b) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing very badly corroded (5.3.2 (b))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #12**

2019-10-10 13:05

MOT test number

984609345758

Result

✓ Passed

Advice Exhaust back box corroded**MOT #11**

2019-10-10 13:05

MOT test number

497570924050

Result

✗ Failed

Advice Exhaust back box corroded**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10**

2018-10-12 13:35

MOT test number

549535809253

Result

✓ Passed

Advice Exhaust ack box corroded

**MOT #9** 2018-10-12 11:17**MOT test number** 968456465207**Result** ✗ Failed**Advice** Exhaust ack box corroded**DANGEROUS** Offside Front Tyre has a lump, caused by separation or partial failure of its structure
175/65/14t (5.2.3 (d) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
(5.2.3 (d) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
(5.2.3 (d) (i))**MOT #8** 2017-10-12 11:37**MOT test number** 510422147457**Result** ✓ Passed**Advice** Slight play hand brake lever / both rear tyres outer sidewall cracked / o/s/f tyre outer edge
cracked / back box outer skin corroded**MOT #7** 2016-10-06 13:25**MOT test number** 108791257918**Result** ✓ Passed**Advice** Offside Front tyre is cracked and perrished around tread and side wall areas**Advice** Nearside Rear and offside rear tyres are perrished and cracking around tread and sidewall areas**Advice** The exhaust back box is in poor condition**MOT #6** 2015-10-14 08:08**MOT test number** 853266879413**Result** ✓ Passed**MOT #5** 2015-03-04 13:28**MOT test number** 379633765023**Result** ✓ Passed

**MOT #4** 2014-03-06 15:48**MOT test number** 325955964039**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #3** 2014-03-06 12:10**MOT test number** 706315364049**Result** ✗ Failed**Fail** Nearside Rear rear brake binding (3.7.B.1)**Notice** Items removed from driver's view prior to test**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #2** 2013-04-04 17:07**MOT test number** 916824293015**Result** ✓ Passed**MOT #1** 2013-04-02 13:55**MOT test number** 849352293083**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
26 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YK10NGV
Plate since	2019-03-28
Current registration	YK10NGV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-01
Last registration	2024-02-27
Complete history	See info



Registration #1	2010-03-01	21 mi
Registration #2	2013-04-02	15.016 mi
Registration #3	2013-04-04	15.018 mi
Registration #4	2014-03-06	18.347 mi
Registration #5	2014-03-06	18.347 mi
Registration #6	2015-03-04	21.656 mi
Registration #7	2015-10-14	23.756 mi
Registration #8	2016-10-06	25.508 mi
Registration #9	2017-10-12	27.712 mi
Registration #10	2018-10-12	30.483 mi
Registration #11	2019-05-29	30.577 mi
Registration #12	2019-05-29	30.577 mi
Registration #13	2019-05-29	30.577 mi
Registration #14	2019-05-29	30.577 mi
Registration #15	2019-05-29	30.577 mi
Registration #16	2019-05-29	30.577 mi
Registration #17	2019-05-29	30.577 mi
Registration #18	2019-05-29	30.577 mi
Registration #19	2019-05-29	30.577 mi
Registration #20	2019-05-29	30.577 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203