



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2010
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-09-26
Pictures	21
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-24
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	26
Total items failed	6

MOT #16	2023-10-18 11:34
MOT test number	581643872686
Result	✓ Passed
Next expiry date	2024-10-17
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2023-10-17 13:38
MOT test number	903519122756
Result	✗ Failed
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))

**MOT #14** 2022-10-01 12:30**MOT test number** 663778230192**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #13** 2021-10-07 15:11**MOT test number** 174818611355**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking / perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking / perishing (5.2.3 (d) (ii))**MOT #12** 2021-10-07 14:25**MOT test number** 922123393293**Result** ✗ Failed**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking / perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking / perishing (5.2.3 (d) (ii))**MOT #11** 2020-10-22 13:53**MOT test number** 886647994788**Result** ✓ Passed**MOT #10** 2019-04-18 15:22**MOT test number** 412485336819**Result** ✓ Passed

**MOT #9** 2018-05-10 15:27**MOT test number** 736964499557**Result** ✓ Passed**MOT #8** 2018-05-10 11:36**MOT test number** 154132477732**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2017-04-19 09:48**MOT test number** 810855770520**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner back (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #6** 2016-05-03 12:31**MOT test number** 621161653122**Result** ✓ Passed**MOT #5** 2015-05-13 16:59**MOT test number** 685073035177**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #4** 2015-05-09 11:59**MOT test number** 597329125126**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Fail** Rear fog lamp not working (1.3.2b)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Rear fog lamp tell tale not working (1.3.1b)**MOT #3** 2014-05-09 17:25**MOT test number** 695139524130**Result** ✓ Passed**MOT #2** 2014-05-09 14:53**MOT test number** 267169824193**Result** ✗ Failed**Fail** Rear fog lamp switch faulty (1.3.1a)**Fail** Rear fog lamp not working (1.3.2b)**MOT #1** 2013-05-08 15:18**MOT test number** 596518423140**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LM10LYK
Plate since	2024-03-28
Current registration	 LM10LYK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-13
Last registration	2023-10-18
Complete history	See info



Registration #1	2010-05-13	11 mi
Registration #2	2013-05-08	10.811 mi
Registration #3	2014-05-09	14.151 mi
Registration #4	2014-05-09	14.151 mi
Registration #5	2015-05-09	17.585 mi
Registration #6	2015-05-13	17.625 mi
Registration #7	2016-05-03	20.187 mi
Registration #8	2017-04-19	22.677 mi
Registration #9	2018-05-10	24.399 mi
Registration #10	2018-05-10	24.399 mi
Registration #11	2019-05-20	25.277 mi
Registration #12	2019-05-20	25.277 mi
Registration #13	2019-05-20	25.277 mi
Registration #14	2019-05-20	25.277 mi
Registration #15	2019-05-20	25.277 mi
Registration #16	2019-05-20	25.277 mi
Registration #17	2019-05-20	25.277 mi
Registration #18	2019-05-20	25.277 mi
Registration #19	2019-05-20	25.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 081719