



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T200 L SWB P/V
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-01
MOT pass rate	50 %
MOT passed	13
Failed MOT tests	13
Total advice items	51
Total items failed	73

MOT #26	2024-04-02 13:53
MOT test number	850802700604
Result	✓ Passed
Next expiry date	2025-04-01
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #25**

2024-03-21 09:37

MOT test number

972054738788

Result

✗ Failed

- Advice** Front Coil spring corroded nearside & offside (5.3.1 (b) (i))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect lens deteriorated (4.1.2 (c))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Rear Service brake fluctuating, but not excessively nearside & offside (1.2.1 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect lens deteriorated (4.1.2 (c))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively nearside & offside (3.4 (b) (ii))

MOT #24

2023-03-16 11:06

MOT test number

936016707706

Result

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #23	2023-03-08 12:17
MOT test number	303295212359
Result	✗ Failed
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))
Minor	Offside Headlamp lens slightly defective deteriorated (4.1.1 (b) (i))
Fail	Offside Rear Service brake lagging in operation (1.2.1 (d))
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Minor	Nearside Headlamp lens slightly defective deteriorated (4.1.1 (b) (i))
Fail	Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted end cap missing (6.1.4 (a) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #22	2022-03-10 15:07
MOT test number	979378441752
Result	✓ Passed

MOT #21	2022-01-31 12:13
MOT test number	971357672997
Result	✗ Failed
Fail	Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
Fail	Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))
Fail	Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill (6.1.1 (c) (i))



MOT #20	2020-06-18 15:19
MOT test number	760653613957
Result	✓ Passed
Advice	Windscreen marked by wiper blade
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear bumper corner missing
Advice	Tail pipe corrode off

**MOT #19**

2020-06-09 11:44

MOT test number

677672407622

Result**✗ Failed**

- Fail** Power steering malfunctioning steering very tight (2.1.5 (a))
- Fail** Front Tyre has ply or cords exposed both inners (5.2.3 (d) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))
- Advice** Handbrake efforts just pass
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure cut and tread coming apart (5.2.3 (d) (ii))
- Fail** Central Stop lamp(s) not working upper (4.3.1 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Brake pipe inadequately clipped or supported rear to fronts all replaced and not clipped in (1.1.11 (d) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Tail pipe corrode off
- Advice** Offside Rear bumper corner missing
- Fail** Windscreen damaged and affecting the driver's view of the road windscreen marked by wiper blade o/s (3.2 (a) (ii))

**MOT #18**

2019-03-15 08:31

MOT test number

267113655079

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Steering system slightly rough (2.1.1 (a))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17

2019-03-11 14:47

MOT test number

186466768590

Result

✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2018-08-15 12:52

MOT test number

932588852082

Result**✗ Failed**

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Offside Front Inner Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Minor Brake pipe inadequately clipped or supported front to rear x2 (1.1.11 (d) (i))

Advice High level stop lamp not working

Fail Steering system excessively rough (2.1.1 (a))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps x2 (4.7.1 (b) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15

2016-10-04 15:17

MOT test number

267919898232

Result**✓ Passed**

Advice Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)

**MOT #14**

2016-09-21 09:06

MOT test number

466289615333

Result

✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)
- Fail** Offside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #13

2016-09-06 10:24

MOT test number

795163403871

Result

✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Service brake: efficiency below requirements (3.7.B.7)

MOT #12

2015-08-27 07:56

MOT test number

944768733575

Result

✓ Passed

**MOT #11**

2015-08-18 00:00

MOT test number

632830847502

Result

✗ Failed

- Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Rear brake application uneven (3.7.B.2)
- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside rear brake binding (3.7.B.1)

MOT #10

2014-08-22 12:51

MOT test number

725604234281

Result

✓ Passed

MOT #9

2014-08-22 12:31

MOT test number

865394234228

Result

✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #8

2013-08-23 14:32

MOT test number

326845133267

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7** 2013-08-23 12:35**MOT test number** 478415033209**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2012-08-23 12:47**MOT test number** 938236932252**Result** ✓ Passed**MOT #5** 2012-08-16 15:04**MOT test number** 509529022251**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear registration plate deteriorated (6.3.1d)**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Front registration plate deteriorated (6.3.1d)



MOT #4 2011-08-26 09:56

MOT test number 398308831276

Result ✓ Passed

- Notice** N/s inner c.v. boot split.
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #3 2011-08-23 13:00

MOT test number 756185831219

Result ✗ Failed

- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** N/s inner c.v. boot split.
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2010-09-01 10:15

MOT test number 861744340210

Result ✓ Passed

- Notice** N/s inner c.v.boot split



MOT #1	2009-08-28 09:38
MOT test number	304800249420
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
1 April 2025

Tax status		Valid until 1 September
Days left		124
MOT expiry date		1 April 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-09-01
Last registration	2024-04-02
Complete history	See info



Registration #1	2006-09-01	8 mi
Registration #2	2009-08-28	67.004 mi
Registration #3	2010-09-01	88.649 mi
Registration #4	2011-08-23	108.678 mi
Registration #5	2011-08-26	108.699 mi
Registration #6	2012-08-16	89.300 mi
Registration #7	2012-08-23	129.408 mi
Registration #8	2013-08-23	147.827 mi
Registration #9	2013-08-23	147.831 mi
Registration #10	2014-08-22	166.577 mi
Registration #11	2014-08-22	166.577 mi
Registration #12	2015-08-18	182.572 mi
Registration #13	2015-08-27	183.003 mi
Registration #14	2016-09-06	36.487 mi
Registration #15	2016-09-06	36.487 mi
Registration #16	2016-09-06	36.487 mi
Registration #17	2016-09-06	36.487 mi
Registration #18	2016-09-06	36.487 mi
Registration #19	2016-09-06	36.487 mi
Registration #20	2016-09-06	36.487 mi
Registration #21	2016-09-06	36.487 mi
Registration #22	2016-09-06	36.487 mi
Registration #23	2016-09-06	36.487 mi
Registration #24	2016-09-06	36.487 mi
Registration #25	2016-09-06	36.487 mi
Registration #26	2016-09-06	36.487 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1410 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	6Y16583