





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Black
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2021-09-19

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-10-04
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #14	2023-09-29 12:30
MOT test number	563070275357
Result	✓ Passed
Next expiry date	2024-10-04

MOT #13	2023-09-22 12:58
MOT test number	310433053695
Result	X Failed
Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))	
Fail Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))	

MOT #12		2022-09-23 10:51
MOT test	number	634155334945
Result		✓ Passed
Advice Rear bush	Nearside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	g in excessive movement
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Rear bush	Offside Front Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	n excessive movement
Advice (ii))	Front Inner Brake disc worn, pitted or scored, but not seriously weakene	ed Both sides (1.1.14 (a)

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11 2021-10-05 10:07

MOT test number 223163284984

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

MOT #10 2021-10-04 13:16

MOT test number 516702868632

Result X Failed

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

Fail Windscreen washer not working (3.5 (a))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear most (5.3.4 (a) (i))

MOT #9 2021-01-15 17:45

MOT test number 933923604641

Result ✓ Passed

MOT #8 2020-01-15 16:59

MOT test number 787611272696

Result \(\sqrt{Passed} \)

MOT #7 2019-01-21 17:33

MOT test number 337324650041

MOT #6 2018-01-15 16:42

MOT test number 978924707377

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2017-01-16 17:41
MOT test number	113670905574
Result	✓ Passed
MOT #4	2016-01-11 17:09
MOT test number	957411168033
Result	✓ Passed
MOT #3	2015-01-14 16:32
MOT test number	107374715065
Result	✓ Passed
MOT #2	2014-01-16 12:33
MOT test number	695576814067
Result	✓ Passed
MOT #1	2013-01-09 11:54
MOT test number	158399303409
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



ND59WTG report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owr		h:a	+~	100
UVVI	161	mis	шО	II V

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-22
Last registration	2023-09-29
Complete history	See info



Registration #1	2010-01-22	20 mi
Registration #2	2013-01-09	22.251 mi
Registration #3	2014-01-16	29.133 mi
Registration #4	2015-01-14	35.526 mi
Registration #5	2016-01-11	41.583 mi
Registration #6	2017-01-16	47.013 mi
Registration #7	2018-01-15	52.766 mi
Registration #8	2019-01-21	58.109 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number AL38072