



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS GRAND PICASSO
Colour	Black
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-24
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18	2021-12-30 18:29
MOT test number	198221251036
Result	✓ Passed
Next expiry date	2022-12-29

MOT #17	2021-12-30 18:29
MOT test number	294238169389
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16	2020-11-25 15:07
MOT test number	819439705578
Result	✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 215/55R16 (5.2.3 (e))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #15	2020-11-25 09:21
MOT test number	897080679343
Result	✗ Failed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm 215/55R16 (5.2.3 (e))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 215/55R16 (5.2.3 (e))

**MOT #14** 2020-01-11 15:56**MOT test number** 528567022849**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge 1.6mm 215/55/16 (5.2.3 (e))**MOT #13** 2018-12-22 16:55**MOT test number** 741002942555**Result** ✓ Passed**MOT #12** 2017-12-23 15:48**MOT test number** 342069868312**Result** ✓ Passed**MOT #11** 2017-12-21 12:13**MOT test number** 195023711403**Result** ✗ Failed**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Parking (secondary) brake grabbing severely (3.7.D.3b)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2016-12-13 11:34**MOT test number** 578406449373**Result** ✓ Passed

**MOT #9** 2015-12-19 13:10**MOT test number** 931045899802**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Nail in NSR tyre**Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)**Advice** Play in steering inner joints**MOT #8** 2015-12-18 09:33**MOT test number** 512979834530**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 2mm and worn on outer edge (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Nail in NSR tyre**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)**Advice** Play in steering inner joints**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2014-12-10 11:16**MOT test number** 719054944326**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-12-10 11:16**MOT test number** 366224044364**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-12-10 09:53**MOT test number** 766394443338**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-12-07 09:04**MOT test number** 108542242345**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight noise from steering on lock to lock**Notice** Under-trays fitted obscuring some underside components**Notice** Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3 2011-12-20 16:54

MOT test number 346744451341

Result ✓ Passed

- Notice** Slight bind to offside front brake
- Notice** Rear brake pads moveing in calipers(noise when rotateing wheels at rears)
- Notice** Front brake discs worn

MOT #2 2010-12-30 15:54

MOT test number 444494460326

Result ✓ Passed

- Notice** Rear brake discs slightly groved and pitted..osfb/disc ijnnerwear ..ok at time of test

MOT #1 2010-12-30 15:54

MOT test number 532604960333

Result ✗ Failed

- Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Notice** Rear brake discs slightly groved and pitted..osfb/disc ijnnerwear ..ok at time of test



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	GD57PSU
Plate since	2024-03-28
Current registration	GD57PSU
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-01
Last registration	2021-12-30
Complete history	See info



Registration #1	2008-01-01	8 mi
Registration #2	2010-12-30	28.604 mi
Registration #3	2011-12-20	35.569 mi
Registration #4	2012-12-07	40.807 mi
Registration #5	2013-12-10	47.206 mi
Registration #6	2014-12-10	53.826 mi
Registration #7	2015-12-18	61.662 mi
Registration #8	2015-12-19	61.662 mi
Registration #9	2016-12-13	64.310 mi
Registration #10	2016-12-13	64.310 mi
Registration #11	2016-12-13	64.310 mi
Registration #12	2016-12-13	64.310 mi
Registration #13	2016-12-13	64.310 mi
Registration #14	2016-12-13	64.310 mi
Registration #15	2016-12-13	64.310 mi
Registration #16	2016-12-13	64.310 mi
Registration #17	2016-12-13	64.310 mi
Registration #18	2016-12-13	64.310 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0002257