



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	CASCADA ELITE S/S
Colour	Black
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	140 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.362 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 2

Date	2023-03-01
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-04
Pictures	21
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2024-03-16
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	28
Total items failed	4

MOT #12	2023-03-17 09:06
MOT test number	437220323312
Result	✓ Passed
Next expiry date	2024-03-16

MOT #11	2023-03-16 14:52
MOT test number	407536536575
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10	2022-01-28 12:36
MOT test number	171901971332
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2021-02-01 15:30
MOT test number	115959353678
Result	✓ Passed

**MOT #8** 2021-02-01 09:40**MOT test number** 811432691139**Result** ✗ Failed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-01-11 14:36**MOT test number** 154171290301**Result** ✓ Passed**Advice** Offside Rear Nail in tyre In tread**Advice** Front Brake disc worn, but not excessively Nearside and offside - lipped (1.1.14 (a) (i))**Advice** Coolant leak From around thermostat housing**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Items removed from driver's view prior to test**Advice** Oil leak, but not excessive From offside engine area (8.4.1 (a) (i))

**MOT #6** 2020-01-11 14:00**MOT test number** 877146479632**Result** ✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Oil leak, but not excessive From offside engine area (8.4.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Nail in tyre In tread
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Coolant leak From around thermostat housing
- Advice** Front Brake disc worn, but not excessively Nearside and offside - lipped (1.1.14 (a) (i))

**MOT #5** 2019-01-12 11:18**MOT test number** 794873043151**Result** ✓ Passed

- Advice** Offside Front tyre warn inner edge
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front tyre warn inner edge

**MOT #4** 2019-01-11 09:15**MOT test number** 994469887369**Result** ✗ Failed

- Advice** Offside Front tyre warn inner edge
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front tyre warn inner edge

**MOT #3** 2018-01-12 10:19**MOT test number** 329257924229**Result** ✓ Passed**Advice** Fuel cap seal starting to perish**MOT #2** 2017-01-05 09:45**MOT test number** 171641257046**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear tyre perished and worn on edges**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre perished and worn on edges**MOT #1** 2016-01-19 09:21**MOT test number** 259555006320**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 March 2025

✗  
**MOT**  
  
Expired:  
16 March 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-13
Last registration	2023-03-17
Complete history	<a href="#">See info</a>



Registration #1	2013-03-13	6 mi
Registration #2	2016-01-19	14.600 mi
Registration #3	2017-01-05	30.232 mi
Registration #4	2018-01-12	45.746 mi
Registration #5	2019-01-11	60.070 mi
Registration #6	2019-01-12	60.070 mi
Registration #7	2020-01-11	72.426 mi
Registration #8	2020-01-11	72.426 mi
Registration #9	2020-01-11	72.426 mi
Registration #10	2020-01-11	72.426 mi
Registration #11	2020-01-11	72.426 mi
Registration #12	2020-01-11	72.426 mi
Registration #13	2020-01-11	72.426 mi
Registration #14	2020-01-11	72.426 mi
Registration #15	2020-01-11	72.426 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1626 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A14NET -19CH7558LUJ