





report date: 2024-03-29

General information

Make	MINI
Model	COOPER SD COOPER
Colour	Black
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 1

Date 2021-11-21

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-05
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #11	2023-11-30 13:31	
MOT test number	883097616853	
Result	✓ Passed	
Next expiry date	2024-12-05	
Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning & offside (4.3.1 (a) (i)) Advice Front Sub-frame corroded but not seriously weakened & rear (5.3.3 (b) (i))		

MOT #10		2022-12-03 11:29
MOT test	number	698806870521
Result		✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	
Advice	Advice Front Sub-frame corroded but not seriously weakened marked in yellow (5.3.3 (b) (i))	
Advice	Offside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #9 2022-12-03 11:29

MOT test number 438253377945

Result X Failed

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Front Sub-frame corroded but not seriously weakened marked in yellow (5.3.3 (b) (i))

Pass with rectification Offside Headlamp aim too low and too far to the right. (4.1.2 (a))

Advice Offside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Pass with rectification Nearside Headlamp aim too far to the right (4.1.2 (a))

MOT #8 2021-12-06 18:22

MOT test number 495760273685

MOT #7 2021-02-12 08:46

MOT test number 145832168341

Result
✓ Passed

MOT #6 2020-02-06 14:02

MOT test number 141774770765

Result

Passed

MOT #5 2019-02-22 08:37

MOT test number 130980257210

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2018-02-17 11:31
MOT test	number	794915777798
Result		✓ Passed
Advice	Nearside Front suspension has slight movement at a wishbone pin or bush (2.5	.A.1c)
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

Advice Tront brake disc worm, pitted or scored, but not seriously weakened (3.3.11)		
MOT #3	2017-02-23 09:47	
MOT test number	661562128438	
Result	✓ Passed	
MOT #2	2016-02-11 11:58	
MOT test number	523417301257	
Result	✓ Passed	
MOT #1	2015-02-18 11:11	
MOT test number	495509545093	
Result	✓ Passed	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	5 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

MF12SVV

report date: 2024-03-29

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-01
Last registration	2023-11-30
Complete history	See info



Registration #1	2012-03-01	9 mi
Registration #2	2015-02-18	31.238 mi
Registration #3	2016-02-11	36.332 mi
Registration #4	2017-02-23	42.998 mi
Registration #5	2018-02-17	48.736 mi
Registration #6	2019-02-22	54.494 mi
Registration #7	2020-02-06	57.846 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 44
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.377 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12