



report date: 2024-03-29

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Black
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.7 mpg
CO2 emission	192 g/km
CO2 label	J








Internet history

Entry 1

Date	2021-12-15
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	25
Total items failed	8

MOT #15	2023-11-01 11:44
MOT test number	908843797520
Result	✓ Passed
Next expiry date	2024-10-31

MOT #14	2022-11-01 16:23
MOT test number	514187641203
Result	✓ Passed

MOT #13	2021-12-29 11:53
MOT test number	801551399025
Result	✓ Passed

**Advice** Front and rear suspension has surface corrosion/rust but does not effect the operation of any part

MOT #12	2020-12-14 11:10
MOT test number	250863100612
Result	✓ Passed

**Advice** Underneath all corroded suspension & steering components corroded

**MOT #11** 2020-12-14 11:10**MOT test number** 547790796349**Result** ✗ Failed

**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Underneath all corroded suspension & steering components corroded

**MOT #10** 2019-06-07 09:30**MOT test number** 793694638005**Result** ✓ Passed

**Minor** Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Parking brake lever has excessive travel

**MOT #9** 2019-06-07 09:30**MOT test number** 825138394492**Result** ✗ Failed

**Advice** Parking brake lever has excessive travel

**Pass with rectification** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**Minor** Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2018-06-09 14:20**MOT test number** 221192023754**Result** ✓ Passed

**Advice** O/S N/S FRONT TYRES ARE WORN ON INNER EDGES

**MOT #7**

2018-06-08 09:51

**MOT test number**

918279935591

**Result**

✗ Failed

**Advice** O/S N/S FRONT TYRES ARE WORN ON INNER EDGES**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #6**

2017-06-07 09:59

**MOT test number**

624597413669

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Covers fitted not allowing full inspection**Advice** Oil leak**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #5**

2016-06-07 14:33

**MOT test number**

899915960752

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit AND WORN ON OUTER EDGE (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit AND WORN ON OUTER EDGE (4.1.E.1)**Advice** Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** EMISSION NOT REGISTERED

**MOT #4** 2016-06-07 14:33**MOT test number** 138263768587**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Wheel nut(s) missing (4.2.A.1e)**Advice** Offside Front Tyre worn close to the legal limit AND WORN ON OUTER EDGE (4.1.E.1)**Advice** EMISSION NOT REGISTERED**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit AND WORN ON OUTER EDGE (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2015-06-06 11:13**MOT test number** 698767755136**Result** ✓ Passed**MOT #2** 2014-06-02 15:11**MOT test number** 265783654169**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2013-06-12 12:09**MOT test number** 296303763137**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
31 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	31 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>BT10SZN</b>
Plate since	2019-03-29
Current registration	<b>BT10SZN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-09
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2010-07-09	11 mi
Registration #2	2013-06-12	42.251 mi
Registration #3	2014-06-02	52.206 mi
Registration #4	2015-06-06	59.492 mi
Registration #5	2016-06-07	68.329 mi
Registration #6	2016-06-07	68.329 mi
Registration #7	2017-06-07	81.916 mi
Registration #8	2018-06-08	96.959 mi
Registration #9	2018-06-09	97.045 mi
Registration #10	2019-06-09	101.277 mi
Registration #11	2019-06-09	101.277 mi
Registration #12	2019-06-09	101.277 mi
Registration #13	2019-06-09	101.277 mi
Registration #14	2019-06-09	101.277 mi
Registration #15	2019-06-09	101.277 mi
Registration #16	2019-06-09	101.277 mi
Registration #17	2019-06-09	101.277 mi

More info >



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1715 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ704009380