



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 105BHP
Colour	Grey
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-03
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	20
Total items failed	2

MOT #13	2023-12-04 14:09
MOT test number	901137584525
Result	✓ Passed
Next expiry date	2024-12-03

MOT #12	2022-09-13 13:59
MOT test number	275788829394
Result	✓ Passed

MOT #11	2021-09-16 15:30
MOT test number	620161145918
Result	✓ Passed

**MOT #10** 2021-09-14 14:52**MOT test number** 638376436871**Result** ✗ Failed**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure tread (5.2.3 (d) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2021-07-16 12:44**MOT test number** 206134206224**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Both front tyres worn on both shoulders**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2019-07-19 10:14**MOT test number** 451841685231**Result** ✓ Passed**MOT #7** 2018-07-18 10:26**MOT test number** 411590442495**Result** ✓ Passed

**MOT #6** 2018-07-18 10:25**MOT test number** 825653375231**Result** ✗ Failed

Pass with rectification Nearside Stop lamp(s) lens defective such that the emitted light is adversely affected (4.3.1 (b) (ii))

MOT #5 2017-07-20 08:17**MOT test number** 861748841049**Result** ✓ Passed**MOT #4** 2017-07-18 14:38**MOT test number** 528103626162**Result** ✗ Failed

Fail Front Brakes imbalanced across an axle (3.7.B.5b)

MOT #3 2016-04-28 08:24**MOT test number** 745891894247**Result** ✓ Passed

Advice Engine covers fitted under trays fitted

Advice Both rear tyres cracking on outer edges of tread

MOT #2 2015-04-28 09:13**MOT test number** 749918615156**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Small cracks to both rear tyre treads

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components



MOT #1	2014-05-01 09:39
MOT test number	528261624114
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Notice	Front wipers smearing
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
3 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-05
Last registration	2023-12-04
Complete history	See info



Registration #1	2011-05-05	11 mi
Registration #2	2014-05-01	38.617 mi
Registration #3	2015-04-28	47.804 mi
Registration #4	2016-04-28	56.905 mi
Registration #5	2017-07-18	64.723 mi
Registration #6	2017-07-20	64.724 mi
Registration #7	2018-07-18	72.102 mi
Registration #8	2018-07-18	72.102 mi
Registration #9	2019-05-20	72.102 mi
Registration #10	2019-05-20	72.102 mi
Registration #11	2019-05-20	72.102 mi
Registration #12	2019-05-20	72.102 mi
Registration #13	2019-05-20	72.102 mi
Registration #14	2019-05-20	72.102 mi
Registration #15	2019-05-20	72.102 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1460 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

BSW 022728