



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO GTD
Colour	Blue
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-07-18
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-17
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-12
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #13	2023-07-04 09:48
MOT test number	898008485482
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Offside Rear Shock absorber dust cover worn

MOT #12	2022-06-30 12:59
MOT test number	758521984591
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11	2021-07-13 12:07
MOT test number	264357194658
Result	✓ Passed

**MOT #10**

2021-03-22 15:48

MOT test number

471847851056

Result

✓ Passed

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #9**

2021-03-22 13:11

MOT test number

554766917554

Result

✗ Failed

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn front arm, rear bush (5.3.4 (a) (i))**MOT #8**

2020-03-18 11:28

MOT test number

332004918949

Result

✓ Passed

MOT #7

2019-03-01 09:34

MOT test number

425117436333

Result

✓ Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Tracking check**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2018-03-09 12:27**MOT test number** 810017704200**Result** ✓ Passed**MOT #5** 2017-03-21 17:04**MOT test number** 582947075252**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Centre Exhaust clamp corroded**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-03-15 16:03**MOT test number** 516159532102**Result** ✓ Passed**MOT #3** 2015-03-26 14:08**MOT test number** 589105685072**Result** ✓ Passed**MOT #2** 2014-03-21 12:47**MOT test number** 237630984028**Result** ✓ Passed**MOT #1** 2013-03-11 11:44**MOT test number** 925530273048**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	NU10RBZ
Plate since	2019-03-29
Current registration	NU10RBZ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-27
Last registration	2023-07-04
Complete history	See info



Registration #1	2010-03-27	20 mi
Registration #2	2013-03-11	27.481 mi
Registration #3	2014-03-21	37.116 mi
Registration #4	2015-03-26	46.870 mi
Registration #5	2016-03-15	51.904 mi
Registration #6	2017-03-21	58.890 mi
Registration #7	2018-03-09	67.969 mi
Registration #8	2019-03-01	77.631 mi
Registration #9	2020-03-01	85.377 mi
Registration #10	2021-03-01	93.123 mi
Registration #11	2022-03-01	100.869 mi
Registration #12	2023-03-01	108.615 mi
Registration #13	2024-03-01	116.361 mi
Registration #14	2025-03-01	124.107 mi
Registration #15	2026-03-01	131.853 mi
Registration #16	2027-03-01	139.599 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CBB319694