




report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD ALL4
Colour	Blue
Year of manufacture	2012
Top speed	120 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-25
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-08-21
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #10 2021-07-22 08:37**MOT test number** 332855727965**Result** Passed**Next expiry date** 2022-07-26

- Advice** Under-trays fitted obscuring some testable components
- Advice** Steering column universal joint has slight wear or play (2.2.2 (c))
- Advice** Steering system slightly rough (2.1.1 (a))

MOT #9 2020-07-27 12:23**MOT test number** 959296141710**Result** Passed

- Advice** Steering system slightly rough (2.1.1 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Lower Steering column universal joint has slight wear or play (2.2.2 (c))



MOT #8	2020-07-24 07:43
MOT test number	984807681720
Result	✗ Failed
Advice	Steering system slightly rough (2.1.1 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Lower Steering column universal joint has slight wear or play (2.2.2 (c))
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #7	2019-04-11 12:07
MOT test number	440477080457
Result	✓ Passed
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt insecure (2.1.3 (g) (i))
Minor	Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #6	2019-03-04 09:53
MOT test number	465656890959
Result	✗ Failed
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Steering system excessively rough (2.1.1 (a))

MOT #5	2018-12-19 13:33
MOT test number	985977235319
Result	✗ Failed
Fail	Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))
Fail	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Central Upper high level stop light inoperative

**MOT #4** 2018-01-05 11:17**MOT test number** 243614414560**Result** Passed**MOT #3** 2018-01-05 11:17**MOT test number** 272324973067**Result** Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2016-12-30 13:53**MOT test number** 624044117410**Result** Passed**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d-bush (2.4.G.2)**Advice** Offside Front tyre worn on inner edge**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement d-bush (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-06-09 09:37**MOT test number** 407700265124**Result** Passed**Notice** O/s/f tyre below 3mm



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YD12MXH
Plate since	2019-09-28
Current registration	YD12MXH
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-06-08
Last registration	2021-07-22
Complete history	See info



Registration #1	2012-06-08	12 mi
Registration #2	2015-06-09	36.279 mi
Registration #3	2016-12-30	56.527 mi
Registration #4	2018-01-05	63.461 mi
Registration #5	2018-01-05	63.461 mi
Registration #6	2018-12-19	67.946 mi
Registration #7	2019-06-20	75.277 mi
Registration #8	2019-06-20	75.277 mi
Registration #9	2019-06-20	75.277 mi
Registration #10	2019-06-20	75.277 mi
Registration #11	2019-06-20	75.277 mi
Registration #12	2019-06-20	75.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1420 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	70898013
---------------	----------