





report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	White
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	11.3 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	178 BHP
Max. torque	420 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg



CarCheck.co.uk page 1/10



## Internet history

#### Entry 3

Date 2021-11-05

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date 2021-11-04

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-08-22

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



PJ63AWZ

report date: 2024-03-29

#### **MOT** history

21-09-06 08:47
ĺ

**MOT test number** 618918773208

**Result** ✓ Passed

Next expiry date 2022-09-05

**MOT #6** 2021-01-28 07:56

**MOT test number** 757314248984

Result \rightarrow Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-05-29 09:47

**MOT test number** 185409662973

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Nearside front body damaged

MOT #4 2020-05-29 08:43

**MOT test number** 380377605979

Result X Failed

Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Nearside front body damaged

MOT #3 2019-01-07 17:35

**MOT test number** 138292390216

CarCheck.co.uk page 3/10



MOT #2

MOT test number

898252188131

Result

Advice Emissions too low to register

MOT #1

MOT test number

495626092764

Result

Advice Emissions too low to register (DPF) fitted.

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

Type

Damage 2

**Date** 

**Category** 

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*********	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 8/10



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-05
Last registration	2021-09-06
Complete history	See info



Registration #1	2013-12-05	18 mi
Registration #2	2016-11-11	64.085 mi
Registration #3	2017-11-27	88.081 mi
Registration #4	2019-01-07	93.806 mi
Registration #5	2020-05-29	116.562 mi
Registration #6	2020-05-29	116.563 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		19.397-es

More info >

CarCheck.co.uk page 9/10



## Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



# Dimensions & weight

Width	2228 mm
Height	1834 mm
Length	5254 mm
Kerb weight	2093 kg
Max. allowed weight	3170 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

CarCheck.co.uk page 10/10

Engine number CSHA044337