



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-18
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-25
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	34
Total items failed	6

MOT #152022-04-26 08:49

MOT test number453103065207

Result✓ Passed

Next expiry date2023-04-25

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm on the centre. (5.2.3 (e))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Trailing arm bushes worn on both side. (5.1.2 (b) (i))
- Advice** Sub-frame corroded but not seriously weakened Front and Rear. (5.3.3 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension top mount has a play and noisy when steering.
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm on the centre. and cracked/perished. (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule Both side. (1.1.12 (f) (i))
- Advice** Corrosion all around, suspension components/coil springs/braking/antiroll bar and brackets/inner and outer sills/chassis, but not seriously weakened.

**MOT #14**

2022-04-22 11:02

**MOT test number**

601391242787

**Result****✗ Failed****MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect No pattern (4.1.2 (c))**Advice** Rear Brake hose has slight corrosion to ferrule Both side. (1.1.12 (f) (i))**Minor** Windscreen wiper blade defective Both smearing (3.4 (b) (i))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Trailing arm bushes worn on both side. (5.1.2 (b) (i))**Advice** Nearside Front Suspension top mount has a play and noisy when steering.**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect No pattern (4.1.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm on the centre. and cracked/perished. (5.2.3 (e))**Advice** Sub-frame corroded but not seriously weakened Front and Rear. (5.3.3 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Corrosion all around, suspension components/coil springs/braking/antiroll bar and brackets/inner and outer sills/chassis, but not seriously weakened.**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm on the centre. (5.2.3 (e))**MOT #13**

2021-06-04 13:18

**MOT test number**

594899565990

**Result****✓ Passed****MOT #12**

2019-05-08 08:43

**MOT test number**

476613642427

**Result****✓ Passed**

**MOT #11** 2019-05-07 09:20**MOT test number** 475552283768**Result** ✗ Failed**Advice** Exhaust outer skin corroded**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**MOT #10** 2019-01-23 12:27**MOT test number** 931852285977**Result** ✓ Passed**MOT #9** 2018-01-25 09:07**MOT test number** 811563183729**Result** ✓ Passed**MOT #8** 2018-01-18 14:43**MOT test number** 366229681238**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Fail** Front brake excessively fluctuating (3.7.B.3)**Fail** Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

**MOT #7** 2017-04-26 13:39**MOT test number** 472414396596**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)

**MOT #6** 2016-04-19 10:00**MOT test number** 314169650320**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-04-13 10:03**MOT test number** 559193505116**Result** ✓ Passed**MOT #4** 2014-03-31 13:08**MOT test number** 787980394054**Result** ✓ Passed**MOT #3** 2013-10-15 10:44**MOT test number** 405778983247**Result** ✓ Passed



MOT #2	2012-12-18 15:36
MOT test number	645993652386
Result	✓ Passed

MOT #1	2012-12-18 10:48
MOT test number	207483452331
Result	✗ Failed

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✕  
Untaxed

Tax expired:  
24 April 2023

✕  
MOT

Expired:  
25 April 2023

Tax status	Expired at 24 April 2023
Days left	371 days too late
MOT expiry date	25 April 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-22
Last registration	2022-04-26
Complete history	<a href="#">See info</a>



Registration #1	2009-12-22	25 mi
Registration #2	2012-12-18	30.712 mi
Registration #3	2012-12-18	30.712 mi
Registration #4	2013-10-15	39.346 mi
Registration #5	2014-03-31	44.902 mi
Registration #6	2015-04-13	50.115 mi
Registration #7	2016-04-19	58.229 mi
Registration #8	2017-04-26	65.898 mi
Registration #9	2018-01-18	70.915 mi
Registration #10	2019-01-22	75.277 mi
Registration #11	2019-01-22	75.277 mi
Registration #12	2019-01-22	75.277 mi
Registration #13	2019-01-22	75.277 mi
Registration #14	2019-01-22	75.277 mi
Registration #15	2019-01-22	75.277 mi
Registration #16	2019-01-22	75.277 mi
Registration #17	2019-01-22	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607