





## General information

MINI
MINI ONE
Silver
2011
116 mph
10.5 seconds
6 speed Manual

### Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D







# Internet history

Entry 1		
Date	2021-05-24	
Pictures	13	
Listing price	View report	









source: autotrader.co.uk



# MOT history

MOT expiry date	2024-06-06
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #13	2023-06-06 07:48
MOT test number	882272259878
Result	✓ Passed
Next expiry date	2024-06-06
Advice Central Exhaust has a minor leak of exhaust gases Flexi joint. (oe) (6.1.2 (a	))
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Rear Lower Gearbox mounting defective	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene (1.1.14 (a) (ii))	d Corrosion setting in.
Advice Oil leak, but not excessive (8.4.1 (a) (i))	



MOT #12	2023-06-01 11:23
MOT test number	470822570618
Result	🗙 Failed
<b>Fail</b> Nearside Parking brake inoperative on one side (1.4.1 (a))	
Advice Park brake travel.	
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Lower Gearbox mounting defective	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	Corrosion setting in.
Advice Central Exhaust has a minor leak of exhaust gases Flexi joint. (oe) (6.1.2 (a))	

MOT #11	2022-06-07 12:08
MOT test number	259531961054
Result	✓ Passed

MOT #10	2022-05-28 14:11
MOT test number	942231984543
Result	🗙 Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Fail</b> Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i)	)

SM11XZA

report date: 2024-03-29



S	Μ	1	1	XZ	Z/	4
1	repo	rt d	ate:	2024	-03-	29

MOT #9		2021-06-03 09:54
MOT #9	numbor	920718395242
	humber	
Result		✓ Passed
Advice	Under trays fitted	
MOT #8	· ·	2020-07-22 14:56
MOT test	number	843702424415
Result		Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides outer e	edges (5.2.3 (e))
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
MOT #7		2019-07-23 08:40
MOT test	number	773347267213
Result		✓ Passed
MOT #6		2018-07-23 08:24
MOT test	number	204467237034
Result		✓ Passed

MOT #5	2017-07-25 10:40
MOT test number	378743837123
Result	✓ Passed
MOT #4	2016-08-26 13:50

MOT #4	2016-08-26 13:50
MOT test number	992384782754
Result	✓ Passed

MOT #3	2016-01-12 14:24
MOT test number	764046030727
Result	✓ Passed





MOT #2		2015-01-13 10:22
MOT test	number	957173015088
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2014-01-21 16:15
MOT test number	456691324084
Result	✓ Passed



Tax & MOT check

√ Taxe	d		✓ MOT
Tax due: 1 June 2024 Tax status		Expires: 6 June 2024	Valid until 1 June
Days left			33
MOT expiry date			6 June 2024
Full MOT history			See MOT history

## Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-29
Last registration	2023-06-06
Complete history	<u>See info</u>



Registration #1	2011-06-29	14 mi
Registration #2	2014-01-21	8.617 mi
Registration #3	2015-01-13	18.198 mi
Registration #4	2016-01-12	29.623 mi
Registration #5	2016-08-26	34.887 mi
Registration #6	2017-07-25	37.169 mi
Registration #7	2018-07-23	39.251 mi
Registration #8	2019-07-23	41.561 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	B560J085