



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 BUSINESS EDITION LUX
Colour	Blue
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B






Internet history

Entry 4

Date	2024-04-13
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 3


Date	2021-12-24
Pictures	19
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-12-23
Pictures	19
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-10-21
Pictures	1



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-11
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #7	2024-04-12 09:00
MOT test number	361396344212
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2023-09-14 11:53
MOT test number	611896632057
Result	✓ Passed

MOT #5	2022-09-01 13:23
MOT test number	263263286668
Result	✓ Passed
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2022-09-01 13:23**MOT test number** 359918544444**Result** ✗ Failed**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))**MOT #3** 2021-11-02 08:46**MOT test number** 577552864476**Result** ✓ Passed**MOT #2** 2021-05-13 11:24**MOT test number** 102533604459**Result** ✓ Passed**MOT #1** 2020-08-18 09:33**MOT test number** 254862512977**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

X

Untaxed

Tax expired:
11 April 2024

✓

MOT

Expires:
11 April 2025

Tax status	Expired at 11 April 2024
Days left	18 days too late
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-09-08
Last registration	2024-04-12
Complete history	See info



Registration #1	2017-09-08	13 mi
Registration #2	2020-08-18	45.112 mi
Registration #3	2021-05-13	45.266 mi
Registration #4	2021-05-13	45.266 mi
Registration #5	2021-11-02	46.461 mi
Registration #6	2021-11-02	46.461 mi
Registration #7	2021-11-02	46.461 mi
Registration #8	2021-11-02	46.461 mi
Registration #9	2021-11-02	46.461 mi
Registration #10	2021-11-02	46.461 mi
Registration #11	2021-11-02	46.461 mi
Registration #12	2021-11-02	46.461 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1899 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1546 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2242087