





report date: 2024-03-28

General information

| Make | CITROEN |
|---------------------|----------------|
| Model | DS3 DSTYLE |
| Colour | Grey |
| Year of manufacture | 2014 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 120 BHP |
|-------------------------|---------------------|
| Max. torque | 160 Nm at 4.200 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 132 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/14



Internet history


Entry 1

Date 2021-02-07

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/14



MOT history

| MOT expiry date | 2025-03-11 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 47 |
| Total items failed | 0 |

| MOT #12 | | 2024-03-12 14:24 |
|---|--|------------------|
| MOT test | number | 437679771344 |
| Result | | ✓ Passed |
| Next expir | y date | 2025-03-11 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | | |
| Advice | Advice Rear Exhaust mounting defective (6.1.2 (a)) | |
| Advice | Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/14



Result

C14WHS

report date: 2024-03-28

MOT #11 2024-03-05 09:52

MOT test number 629014151959

× Failed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i)) **MAJOR**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2023-02-28 15:39

MOT test number 248445884201

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice

Advice Front Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



YC14WHS

report date: 2024-03-28

| MOT #9 | | 2023-02-16 11:55 |
|----------------------|--|-----------------------|
| MOT test | number | 839589143037 |
| Result | | × Failed |
| MAJOR | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |
| MAJOR | Windscreen washer not working (3.5 (a)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a)) | |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (| 1.1.14 (a) (ii)) |
| MAJOR | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| MAJOR the ingress | Nearside Front Outer Drive shaft joint constant velocity boot split or insecure of dirt $(6.1.7 (g) (ii))$ | e, no longer prevents |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened | I (1.1.14 (a) (ii)) |

| MOT #8 | 2022-01-27 13:03 |
|-----------------|------------------|
| MOT test number | 508294538295 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2021-01-23 14:37 |
| MOT test number | 349564311228 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/14



MOT test number

YC14WHS
report date: 2024-03-28

451972454496

MOT #6 2021-01-20 09:33

MOT test number 410288809543

Result X Failed

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front exhaust mounting coroded/broken

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2020-01-17 16:15

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 6/14



MOT #4 2020-01-17 15:00

MOT test number 831364354485

Result X Failed

Advice Items removed from driver's view prior to test

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-01-18 16:11

MOT test number 387930287016

Result ✓ Passed

Advice Front Items removed from driver's view prior to test

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT #2 2017-11-24 14:57

MOT test number 231613255149

Advice Items removed from driver's view prior to test

MOT #1 2016-11-30 12:36

MOT test number 222047086461

Result \rightarrow Passed

CarCheck.co.uk page 7/14



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 11 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| William . | 40 |
|---|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



YC14WHS

report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

YC14WHS

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this CITROEN had different number plates.

More info >

More info >

CarCheck.co.uk page 11/14



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-04-30 |
| Last registration | 2024-03-12 |
| Complete history | See info |



| Registration #1 | 2014-04-30 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-11-30 | 18.930 mi |
| Registration #3 | 2017-11-24 | 21.656 mi |
| Registration #4 | 2019-01-18 | 25.721 mi |
| Registration #5 | 2020-01-17 | 28.098 mi |
| Registration #6 | 2020-01-17 | 28.098 mi |
| Registration #7 | 2021-01-20 | 28.321 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| | | |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 13/14



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| Width | 1708 mm |
|---------------------|---------|
| Height | 1460 mm |
| Length | 3948 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1075 kg |
| Max. allowed weight | 1554 kg |

Additional information

| Fuel tank capacity | 48 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FHCA2082498 |

CarCheck.co.uk page 14/14