





report date: 2024-03-29

General information

Make	HYUNDAI
Model	KONA S
Colour	Orange
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-01

Pictures 46

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

✓ Passed

	~-				
10/1/	TC	h		-	r\ /
1010		ш	51	LUI	l V
	•			-	. ,

Result

MOT expiry date	2024-06-08
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	6
Total items failed	7

MOT #5	2023-06-09 07:25
MOT test number	127936750983
Result	✓ Passed
Next expiry date	2024-06-08

MOT #	4	2023	3-06-01 12:19
MOT to	est number	40	64961502883
Result			X Failed
Pass	with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Fail	Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))		
Fail	Tyre pressure moni	toring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Offside Rear Outer	Seat belt buckle not functioning as intended not locking in. (7.1.2 (d))	
Fail	Electronic stability	control warning lamp indicates a fault (7.12 (e))	

MOT #3	2022-03-03 09:47
MOT test number	109807748691
Result	✓ Passed
MOT #2	2021-04-24 15:04
MOT test number	730002270656

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-04-23 12:13

MOT test number 489523449697

Advice Offside Front Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

,		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full		NDAI

	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK UK	III
Plate since		
Current registration	NK NIZ	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-05-31
Last registration	2023-06-09
Complete history	See info



Registration #1	2018-05-31	19 mi
Registration #2	2021-04-23	38.741 mi
Registration #3	2021-04-24	38.742 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		0.77 sc

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	85%
Pedestrian	62%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1550 mm
Length	4165 mm
Wheel base	2600 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number G3LCHP192506