



General information

Make	VOLKSWAGEN
Model	EOS FSI
Colour	Silver
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg
CO2 emission	198 g/km
CO2 label	J





MOT history

MOT expiry date	2021-02-08
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #12	2020-01-29 12:08
MOT test number	427889642369
Result	✓ Passed
Next expiry date	2021-02-08

MOT #11	2019-01-28 12:41
MOT test number	539049266909
Result	✓ Passed

MOT #10	2018-01-29 14:50
MOT test number	844542855263
Result	✓ Passed

Advice Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front coil spring corroded (2.4.C.1b)

MOT #9	2017-01-26 16:43
MOT test number	418290611783
Result	✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2016-01-22 10:37**MOT test number** 603033878983**Result** ✓ Passed**MOT #7** 2015-02-09 13:56**MOT test number** 429790345049**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2014-01-14 18:14**MOT test number** 886684714099**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2014-01-13 16:13**MOT test number** 898303614020**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2012-12-17 17:44**MOT test number** 936062552301**Result** ✓ Passed**MOT #3** 2011-12-16 16:55**MOT test number** 507850151307**Result** ✓ Passed



MOT #2	2010-11-26 14:53
MOT test number	710870030341
Result	✓ Passed

MOT #1	2009-12-10 11:38
MOT test number	420524749478
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2021

X

MOT

Expired:
8 February 2021

Tax status	Expired at 1 February 2021
Days left	1182 days too late
MOT expiry date	8 February 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DA56KMM
Plate since	2019-06-29
Current registration	DA56KMM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2006-12-22
Last registration	2020-01-29
Complete history	See info



Registration #1	2006-12-22	18 mi
Registration #2	2009-12-10	29.208 mi
Registration #3	2010-11-26	36.564 mi
Registration #4	2011-12-16	45.162 mi
Registration #5	2012-12-17	53.469 mi
Registration #6	2014-01-13	54.930 mi
Registration #7	2014-01-14	54.930 mi
Registration #8	2015-01-29	55.277 mi
Registration #9	2016-01-29	55.277 mi
Registration #10	2017-01-29	55.277 mi
Registration #11	2018-01-29	55.277 mi
Registration #12	2019-01-29	55.277 mi
Registration #13	2020-01-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1481 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Engine number	BVY 092923