



UK

LG6IZSU

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R57) COOPER SD
Colour	Blue
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 2.700 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-07-30
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	3

## MOT #13 2023-09-16 16:34

MOT test number 106331306335

Result ✓ Passed

Next expiry date 2024-09-15

- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #12 2022-09-05 09:28

MOT test number 370220636582

Result ✓ Passed

- Advice** Offside Front Tyre worn on outer edge and slight damage to outer side wall
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Play in steering rack

**MOT #11** 2022-08-02 13:45**MOT test number** 221366546540**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #10** 2021-09-03 11:42**MOT test number** 721688235659**Result** ✓ Passed**MOT #9** 2021-09-03 08:39**MOT test number** 737990698190**Result** ✗ Failed

- MAJOR** Nearside Inner Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Nearside Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #8** 2020-09-05 11:04**MOT test number** 608417817024**Result** ✓ Passed**MOT #7** 2019-09-05 12:38**MOT test number** 279419654957**Result** ✓ Passed

**MOT #6** 2018-08-31 07:51**MOT test number** 750666762469**Result** ✓ Passed**MOT #5** 2018-08-31 07:51**MOT test number** 135789001095**Result** ✗ Failed**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Pass with rectification** Windscreen washer not working (3.5 (a))**Pass with rectification** Brake pad(s) less than 1.5 mm thick rear (1.1.13 (a) (ii))**MOT #4** 2017-08-19 10:31**MOT test number** 429124569048**Result** ✓ Passed**MOT #3** 2016-09-03 08:42**MOT test number** 234708121646**Result** ✓ Passed**MOT #2** 2015-08-15 09:22**MOT test number** 532799343852**Result** ✓ Passed**MOT #1** 2014-09-06 14:09**MOT test number** 877069444296**Result** ✓ Passed**Notice** Multiple stonechips in windscreen**Notice** Cut in n/s/f tyre sidewall



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-07
Last registration	2023-09-16
Complete history	<a href="#">See info</a>



Registration #1	2011-09-07	26 mi
Registration #2	2014-09-06	36.003 mi
Registration #3	2015-08-15	49.903 mi
Registration #4	2016-09-03	65.507 mi
Registration #5	2017-08-19	79.410 mi
Registration #6	2018-08-31	89.717 mi
Registration #7	2018-08-31	89.717 mi
Registration #8	2019-09-05	92.991 mi
Registration #9	2020-09-05	95.277 mi
Registration #10	2021-09-05	97.563 mi
Registration #11	2022-09-05	99.849 mi
Registration #12	2023-09-16	102.135 mi
Registration #13		
Registration #14		
Registration #15		

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	71667897
---------------	----------