

Ford



### General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Brown
Year of manufacture	2014
Top speed	120 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	149 g/km
CO2 label	F







# Internet history

Entry	1
Date	

Pictures

2021-08-02

12

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-03
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #10	2023-09-04 16:07
MOT test number	370728192762
Result	✓ Passed
Next expiry date	2024-09-03
Advice Offside Front brake caliper retaining spring missing	
Advice Nearside Front ball joint steel dust cover was touching disc	

МОТ #9	2022-11-22 16:46
MOT test number	475389079727
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

MOT #8	2021-08-21 15:27
MOT test number	849920293583
Result	✓ Passed
Advice Vehicle presented in wet condition	





MOT #7		2020-10-20 13:49
MOT test	number	191837420157
Result		✓ Passed
MinorOffside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))MinorTrack rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))		

МОТ #6	2020-10-20 13:49	
MOT test number	833004661256	
Result	× Failed	
Pass with rectification	Front Registration plate inscription illegible (0.1 (b))	
<b>Minor</b> Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))		
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

MOT #5	2019-11-15 15:07
MOT test number	764334974816
Result	✓ Passed

MOT #4		2018-11-05 11:03
MOT test n	number	496299607651
Result		✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

МОТ #3	2018-11-05 11:03
MOT test number	806152279392
Result	× Failed
Pass with rectification	Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
Minor Front Windscreer	a damaged but not adversely affecting driver's view (3.2 (a) (i))



CN64OXF
report date: 2024-03-29

MOT #2		2017-09-26 14:54
MOT test	number	162410480198
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.	3.1a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1		2017-09-25 11:09
MOT test number		920572700628
Result		🗙 Failed
Advice Rear Brake pad(	s) wearing thin (3.5.1g)	
Advice Nearside Rear T	yre worn close to the legal limit (4.1.E.1)	
Pass with rectification	Offside Headlamp aim too low (1.8)	
Advice Front Brake pad	(s) wearing thin (3.5.1g)	
Advice Windscreen has	damage to an area less than a 10mm circle within	zone 'A' (8.3.1a)
Advice Offside Rear Tyr	e worn close to the legal limit (4.1.E.1)	
Pass with rectification	Nearside Headlamp aim too low (1.8)	
FailNearside Front Outeprevents the ingress of dirt	er Front constant velocity joint gaiter deteriorated to etc (2.5.C.1a)	o the extent that it no longer



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 November 2024	Expires: 3 September 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	3 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrient registration	
Current registration Pate since	
Carrent registration Fate since Carrent registration	
Carrent registration Foto since Foto since Foto since	8000-20-20





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-09-04
Complete history	See info



Registration #1	2014-09-30	23 mi
Registration #2	2017-09-25	30.547 mi
Registration #3	2017-09-26	30.578 mi
Registration #4	2018-11-05	46.952 mi
Registration #5	2018-11-05	46.952 mi
Registration #6	2019-11-15	55.613 mi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		10.377 mil





### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles	2
Engine number	ET47075