



General information

Make	FORD
Model	GALAXY GHIA TDI
Colour	Blue
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	44.8 mpg
CO2 emission	173 g/km
CO2 label	H







Internet history

Entry 8


Date	2021-09-26
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 7


Date	2021-09-19
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 6

Date	2021-09-06
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 5



Date	2021-08-29
------	------------

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 4

Date


2021-07-21

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date


2021-07-09

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date


2021-06-22

Pictures

5

Listing price


[View report](#)



source: autotrader.co.uk

Entry 1

Date	2021-06-14
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT expiry date** 2023-11-02**MOT pass rate** 78 %**MOT passed** 14**Failed MOT tests** 4**Total advice items** 12**Total items failed** 12**MOT #18** 2022-11-03 18:53**MOT test number** 997995481630**Result** ✓ Passed**Next expiry date** 2023-11-02**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement
shocker top mount (5.3.4 (a) (i))**Advice** Nearside Front Non obligatory mirror damaged**Minor** Front Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))**MOT #17** 2022-10-24 10:15**MOT test number** 315266562242**Result** ✗ Failed**Fail** Rear Shock absorbers has negligible damping effect both rear shockers (5.3.2 (d))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Nearside Front Non obligatory mirror damaged**Minor** Front Suspension arm ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))**Fail** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its
strength within 30cm of a body mounting jacking point (6.2.2 (d) (i))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement
shocker top mount (5.3.4 (a) (i))**Fail** Offside Rear Service brake grabbing severely (1.2.1 (c))

**MOT #16** 2021-09-24 13:28**MOT test number** 222046279273**Result** ✓ Passed**Advice** Both front discs worn and pitted**Advice** Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))**MOT #15** 2020-10-16 11:30**MOT test number** 559793913030**Result** ✓ Passed**Advice** Both front discs worn**MOT #14** 2019-03-23 16:44**MOT test number** 127622576899**Result** ✓ Passed**MOT #13** 2018-03-20 10:05**MOT test number** 194998093097**Result** ✓ Passed**MOT #12** 2017-04-10 11:14**MOT test number** 186997538110**Result** ✓ Passed**MOT #11** 2016-03-24 17:04**MOT test number** 991222506846**Result** ✓ Passed

**MOT #10** 2016-03-24 17:04**MOT test number** 891929065258**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear fog lamp not working (1.3.2b)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)**MOT #9** 2015-04-02 09:39**MOT test number** 147172495064**Result** ✓ Passed**MOT #8** 2015-04-02 09:39**MOT test number** 979572095061**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Exhaust system not adequately supported (7.1.1)**MOT #7** 2014-03-13 09:01**MOT test number** 776092574047**Result** ✓ Passed**MOT #6** 2014-03-13 09:01**MOT test number** 587392274021**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2013-03-11 09:55**MOT test number** 389240973023**Result** ✓ Passed**MOT #4** 2012-03-22 08:50**MOT test number** 875322282085**Result** ✓ Passed**MOT #3** 2011-03-23 11:09**MOT test number** 938742781007**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-03-30 10:20**MOT test number** 120609980409**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #1** 2009-04-07 11:06**MOT test number** 164467999441**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
4 August 2023

✕
MOT

Expired:
2 November 2023

Tax status	Expired at 4 August 2023
Days left	270 days too late
MOT expiry date	2 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GN06JXE
Plate since	2024-03-29
Current registration	GN06JXE
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-03-31
Last registration	2022-11-03
Complete history	See info



Registration #1	2006-03-31	17 mi
Registration #2	2009-04-07	38.898 mi
Registration #3	2010-03-30	50.521 mi
Registration #4	2011-03-23	61.965 mi
Registration #5	2012-03-22	78.678 mi
Registration #6	2013-03-11	92.645 mi
Registration #7	2014-03-13	109.822 mi
Registration #8	2015-04-02	135.259 mi
Registration #9	2016-03-24	156.334 mi
Registration #10	2016-03-24	156.334 mi
Registration #11	2017-04-10	160.607 mi
Registration #12	2018-03-20	161.229 mi
Registration #13	2019-03-23	161.595 mi
Registration #14	2019-03-23	161.595 mi
Registration #15	2019-03-23	161.595 mi
Registration #16	2019-03-23	161.595 mi
Registration #17	2019-03-23	161.595 mi
Registration #18	2019-03-23	161.595 mi
Registration #19	2019-03-23	161.595 mi
Registration #20	2019-03-23	161.595 mi
Registration #21	2019-03-23	161.595 mi
Registration #22	2019-03-23	161.595 mi
Registration #23	2019-03-23	161.595 mi
Registration #24	2019-03-23	161.595 mi
Registration #25	2019-03-23	161.595 mi



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4642 mm
Wheel base	2835 mm
Kerb weight	1666 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	5A17507