





report date: 2024-03-29

#### General information

Make	KIA
Model	CARENS 1 ECODYNAMICS CRDI
Colour	Black
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date	2021-07-12
Pictures	1
Listing price	<u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

## MOT history

MOT expiry date	2024-08-02
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #11		2023-08-03 13:38
MOT test	number	770547100801
Result		✓ Passed
Next expi	ry date	2024-08-02
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	

CarCheck.co.uk page 3/13



Result

LD63NYC

report date: 2024-03-29

✓ Passed

**MOT #10** 2023-07-24 09:07 **MOT test number** 534889095702 Result × Failed Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d)) Fail Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d)) Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d)) **Advice** Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d)) **Advice** 

MOT #9		2022-07-25 09:06
MOT test	number	993097204122
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2021-07-26 14:22
MOT test number	273166349351
Result	<b>✓</b> Passed
MOT #7	2020-10-20 16:15
MOT test number	765354445700

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6 2020-10-20 11:27

**MOT test number** 832068384695

Result × Failed

Fail Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #5 2019-10-23 08:16

**MOT test number** 396576441357

**Result** ✓ Passed

MOT #4 2018-10-23 09:31

**MOT test number** 209152103496

**Result** 
✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2017-10-24 10:08

**MOT test number** 887392635023

Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #2 2016-10-24 09:40

**MOT test number** 162947046331

Result 

Passed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all discs worn (3.5.1i)

Advice Front tyres low on edges

CarCheck.co.uk page 5/13



MOT #1 2016-10-24 08:30

**MOT test number** 778677865593

Result × Failed

**Fail** Offside Front Driver's seat insecure (6.2.A.1)

**Advice** Front tyres low on edges

Advice Brake disc worn, pitted or scored, but not seriously weakened all discs worn (3.5.1i)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	2 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
********	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	AIR SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-11-30
Last registration	2023-08-03
Complete history	See info



Registration #1	2013-11-30	11 mi
Registration #2	2016-10-24	34.752 mi
Registration #3	2016-10-24	34.753 mi
Registration #4	2017-10-24	47.869 mi
Registration #5	2018-10-23	64.287 mi
Registration #6	2019-10-23	79.858 mi
Registration #7	2020-10-20	91.461 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
S0295	
50482	
60501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	76%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1706 kg
Max. allowed weight	2240 kg

# Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1:

Number of axles 2

**Engine number** D4FDDH509076