





report date: 2024-03-29

General information

| Make | KIA |
|---------------------|-------------------------|
| Model | CEED CRDI 1 ECODYNAMICS |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 122 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 126 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 2.750 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 68.9 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 76.4 mpg |
| CO2 emission | 97 g/km |
| CO2 label | Α |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-05

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-10-31 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 0 |

| MOT #11 | 2023-11-01 11:54 |
|------------------|------------------|
| MOT test number | 780599362915 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-31 |

| MOT #10 | | 2023-11-01 08:15 |
|----------|---|------------------|
| MOT test | number | 592745806161 |
| Result | | × Failed |
| MAJOR | Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| MAJOR | Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| MAJOR | Nearside Front Position lamp not working (4.2.1 (a) (ii)) | |

| M | IOT #9 | | 2022-10-22 11:00 |
|---|----------|--|------------------|
| M | IOT test | number | 628070250013 |
| R | esult | | ✓ Passed |
| | Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| | Advice | O/S/R tyre on 3.7mm tread | |
| | Advice | N/S/R tyre on4mm tread | |
| | Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| | Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/12



MOT #8 2021-10-18 12:28

MOT test number 156405363117

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge of tread pattern. (5.2.3 (e))

MOT #7 2020-10-27 08:47

MOT test number 487812688574

Result \(\sqrt{Passed} \)

Advice Offside Front DRL running light not working

Advice Offside Front fog light not working

MOT #6 2020-10-26 12:29

MOT test number 634717726384

Result X Failed

Advice Offside Front DRL running light not working

MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Front fog light not working

MOT #5 2019-10-22 13:13

MOT test number 416713866514

Result
✓ Passed

Advice Offside Front DRL light not working

Advice Offside Front fog light not working

MOT #4 2018-10-24 10:47

MOT test number 374528473069

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #3 2017-10-26 10:06

MOT test number 846492914607

Advice

Nearside Front Washer jet not working, other washer jets providing enough liquid at this time.

MOT #2 2016-10-27 13:22

MOT test number 813917415380

Result ✓ Passed

MOT #1 2015-10-26 09:36

MOT test number 965404741509

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 32 |
| MOT expiry date | 31 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report | |
|--|-------------|
| | |
| ********* | |
| | |
| ************* | |
| | |
| THE STATE OF THE S | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | Moro info |

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact into

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2012-10-28 |
| Last registration | 2023-11-01 |
| Complete history | See info |



| B 1 1 11 114 | 2012 10 20 | 10 |
|------------------|------------|------------|
| Registration #1 | 2012-10-28 | 10 mi |
| Registration #2 | 2015-10-26 | 31.567 mi |
| Registration #3 | 2016-10-27 | 43.303 mi |
| Registration #4 | 2017-10-26 | 58.672 mi |
| Registration #5 | 2018-10-24 | 77.017 mi |
| Registration #6 | 2019-10-22 | 92.396 mi |
| Registration #7 | 2020-10-26 | 103.428 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 88% |
| Pedestrian | 61% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1780 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 4310 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1499 kg |
| Max. allowed weight | 1810 kg |

Additional information

| Fuel tank capacity | 53 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2

Engine number D4FBCZ436056