



Mercedes-Benz



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | MERCEDES-BENZ |
| Model | S-Class S320 CDI |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 149 mph |
| 0 - 60 mph | 7.5 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 231 BHP |
| Max. torque | 540 Nm at 1.600 rpm |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 24.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 34.0 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-02 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

| | |
|-------------------------|--|
| MOT #14 | 2022-07-11 10:40 |
| MOT test number | 172043436963 |
| Result | ✓ Passed |
| Next expiry date | 2023-07-10 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|--------------------------------|--|
| MOT #13 | 2022-07-11 10:40 |
| MOT test number | 636204046997 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) |

| | |
|------------------------|------------------|
| MOT #12 | 2020-10-20 12:46 |
| MOT test number | 240398857758 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #11 | 2020-10-15 11:32 |
| MOT test number | 492918529856 |
| Result | ✗ Failed |
| Fail | Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |
| Fail | Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |
| Fail | Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |
| Fail | Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Fail | Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |

| | |
|------------------------|------------------|
| MOT #10 | 2019-10-24 12:34 |
| MOT test number | 502335801951 |
| Result | ✓ Passed |



| | |
|------------------------|---|
| MOT #9 | 2018-10-23 16:22 |
| MOT test number | 463196946143 |
| Result | ✓ Passed |
| MOT #8 | 2017-10-18 16:16 |
| MOT test number | 877391400018 |
| Result | ✓ Passed |
| MOT #7 | 2016-10-24 09:52 |
| MOT test number | 895076367717 |
| Result | ✓ Passed |
| MOT #6 | 2015-06-02 16:18 |
| MOT test number | 528573755188 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Notice | Offside rear tyre has cut in sidewall |
| MOT #5 | 2014-05-31 12:07 |
| MOT test number | 295401454196 |
| Result | ✓ Passed |
| MOT #4 | 2013-05-31 11:01 |
| MOT test number | 429991853134 |
| Result | ✓ Passed |
| MOT #3 | 2012-06-01 11:53 |
| MOT test number | 495693752150 |
| Result | ✓ Passed |



| | |
|-----------------|--|
| MOT #2 | 2012-05-22 14:09 |
| MOT test number | 966523942105 |
| Result | ✗ Failed |
| Fail | Parking brake is not capable of being maintained in operation by direct mechanical action only (3.1.2) |
| Fail | Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) |
| Fail | Parking brake: efficiency below requirements (3.7.B.7) |

| | |
|-----------------|------------------|
| MOT #1 | 2011-05-09 15:05 |
| MOT test number | 235929521163 |
| Result | ✓ Passed |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2007-12-14 |
| Last registration | 2022-07-11 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-12-14 | 22 mi |
| Registration #2 | 2011-05-09 | 49.992 mi |
| Registration #3 | 2012-05-22 | 53.513 mi |
| Registration #4 | 2012-06-01 | 53.520 mi |
| Registration #5 | 2013-05-31 | 58.039 mi |
| Registration #6 | 2014-05-31 | 61.785 mi |
| Registration #7 | 2015-06-02 | 65.267 mi |
| Registration #8 | 2016-10-24 | 70.225 mi |
| Registration #9 | 2017-05-22 | 75.277 mi |
| Registration #10 | 2018-05-22 | 80.329 mi |
| Registration #11 | 2019-05-22 | 85.381 mi |
| Registration #12 | 2020-05-22 | 90.433 mi |
| Registration #13 | 2021-05-22 | 95.485 mi |
| Registration #14 | 2022-05-22 | 100.537 mi |
| Registration #15 | 2023-05-22 | 105.589 mi |
| Registration #16 | 2024-05-22 | 110.641 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|-------------|---------|
| Width | 1872 mm |
| Height | 1473 mm |
| Length | 5076 mm |
| Wheel base | 3035 mm |
| Kerb weight | 1965 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 90 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

Number of axles

2

Engine number

64293040497268