





report date: 2024-03-29

General information

Make	ТОУОТА
Model	LANDCRUISER ESTATE D-4D LC4
Colour	Silver
Year of manufacture	2012
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	420 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg
CO2 emission	213 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2023-06-18

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2022-06-14

 Pictures
 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-28
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #11	2023-06-29 15:23
MOT test number	651850377581
Result	✓ Passed
Next expiry date	2024-06-28

MOT #10	2022-06-20 16:2	5
MOT test	number 65426726878	7
Result	✓ Passe	d
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))	
Advice	Covers obscuring some components	

MOT #9		2021-10-23 12:14
MOT test	number	641704295448
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively Surfaces worn. (1.1.14 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin Worn low. (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, but not excessively Surfaces worn. (1.1.14 (a) (i))		
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Front Brake pad(s) wearing thin Worn low. (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #8		2020-10-23 14:39
MOT test	number	867437500664
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))		
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2019-04-27 08:29
MOT test number	673378237343
Result	✓ Passed
MOT #6	2018-04-23 11:47
MOT test number 748295449493	
Result	
MOT #5	2018-04-21 14:09
MOT test number	158369257736
Result	X Failed
Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Front Headlamp not working on dipped beam (1.7.5a)	

CarCheck.co.uk page 4/13



/D12PBX

report date: 2024-03-29

MOT #4 2017-04-27 10:20

MOT test number 350279873842

Result ✓ Passed

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Front Brake pad(s) wearing thin (3.5.1g) Advice

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Offside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Vehicles internal headlight adjuster altered to recheck lights

MOT #3 2017-04-27 10:20

MOT test number 607201524728

Result × Failed

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Offside Front Upper Suspension arm ball joint dust cover deteriorated, but preventing the ingress

of dirt (2.4.G.2)

Advice

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #2 2016-03-14 16:31

MOT test number 938120693960

Result Passed

Advice Under trays fitted obsuring some parts

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2015-03-26 09:32

MOT test number 456365285051

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check





Tax status	Expired at 27 April 2024
Days left	3 days too late
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Κ
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

e union matery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIL
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-06
Last registration	2023-06-29
Complete history	See info



Registration #1	2012-04-06	9 mi
Registration #2	2015-03-26	20.235 mi
Registration #3	2016-03-14	24.722 mi
Registration #4	2017-04-27	33.037 mi
Registration #5	2017-04-27	33.037 mi
Registration #6	2018-04-21	49.825 mi
Registration #7	2018-04-23	49.869 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1890 mm
Length	4760 mm
Wheel base	2790 mm
Kerb weight	2415 kg
Max. allowed weight	2990 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number 1KD2134883