



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S
Colour	Red
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





MOT history

MOT expiry date	2025-01-15
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	19
Total items failed	14

MOT #21	2024-01-16 15:23
MOT test number	697316751513
Result	✓ Passed
Next expiry date	2025-01-15
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #20	2023-12-29 09:30
MOT test number	497541471680
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #19**

2022-10-04 11:46

**MOT test number**

829453531307

**Result**

✓ Passed

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Aft bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Aft bush (5.3.4 (a) (i))**MOT #18**

2021-09-16 14:45

**MOT test number**

994325519434

**Result**

✓ Passed

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #17**

2020-09-11 12:51

**MOT test number**

478864337828

**Result**

✓ Passed

**MOT #16**

2019-09-18 13:06

**MOT test number**

832811565465

**Result**

✓ Passed

**MOT #15**

2019-09-18 13:06

**MOT test number**

705174123747

**Result**

✗ Failed

**Pass with rectification** Exhaust system insecure centre mount corroded away. (6.1.2 (a))

**MOT #14** 2018-09-13 08:38**MOT test number** 965666535814**Result** ✓ Passed**MOT #13** 2018-09-13 08:37**MOT test number** 935109068728**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**MOT #12** 2017-09-15 13:45**MOT test number** 421225001513**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases slight blow from exhaust front section when reversing car (7.1.2)**Advice** Front Tyre worn close to the legal limit offside & nearside (4.1.E.1)**MOT #11** 2016-09-14 14:56**MOT test number** 955389140767**Result** ✓ Passed**MOT #10** 2016-09-14 14:56**MOT test number** 938482177977**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #9** 2015-09-18 09:31**MOT test number** 872087352675**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin 2.0mm (3.5.1g)**Advice** Child seat fitted offside rear**MOT #8** 2015-09-10 08:10**MOT test number** 419560474123**Result** ✗ Failed**Advice** Child seat fitted offside rear**Advice** Rear Brake pad(s) wearing thin 2.0mm (3.5.1g)**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #7** 2014-09-15 15:53**MOT test number** 939438954231**Result** ✓ Passed**Notice** Child seat fitted to vehicle**MOT #6** 2014-09-15 13:03**MOT test number** 886838854240**Result** ✗ Failed**Fail** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Notice** Child seat fitted to vehicle

**MOT #5** 2013-09-09 11:27**MOT test number** 209122753283**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-09-07 15:31**MOT test number** 625381252262**Result** ✓ Passed**Notice** Neraside wiper starting to smear screen**MOT #3** 2011-09-05 11:43**MOT test number** 237448341277**Result** ✓ Passed**MOT #2** 2011-09-05 11:43**MOT test number** 696848341238**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2010-09-14 12:11**MOT test number** 864437950288**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
15 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	15 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-29
Last registration	2024-01-16
Complete history	<a href="#">See info</a>



Registration #1	2007-10-29	22 mi
Registration #2	2010-09-14	17.981 mi
Registration #3	2011-09-05	23.484 mi
Registration #4	2012-09-07	29.945 mi
Registration #5	2013-09-09	37.486 mi
Registration #6	2014-09-15	45.519 mi
Registration #7	2014-09-15	45.519 mi
Registration #8	2015-09-10	51.700 mi
Registration #9	2015-09-18	51.953 mi
Registration #10	2016-09-14	58.347 mi
Registration #11	2016-09-14	58.347 mi
Registration #12	2016-09-14	58.347 mi
Registration #13	2016-09-14	58.347 mi
Registration #14	2016-09-14	58.347 mi
Registration #15	2016-09-14	58.347 mi
Registration #16	2016-09-14	58.347 mi
Registration #17	2016-09-14	58.347 mi
Registration #18	2016-09-14	58.347 mi
Registration #19	2016-09-14	58.347 mi
Registration #20	2016-09-14	58.347 mi
Registration #21	2016-09-14	58.347 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N3093351